

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3298H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER CTR MOULDING	CRACKED	451.25	451.25
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER BEAM	CRACKED	394.80	394.80
1	REAR BUMPER LWR MOULDING	сит	155.00	155.00
1	REAR BUMPER STAY LH	NOT NECESSARY	138.10	-
1	REAR BUMPER STAY RH	BENT	138.10	138.10
1	REAR BUMPER SIDE BRKT RH	NOT NECESSARY	55.80	-
1	REAR BUMPER REFLECTOR RH	MISSING	41.45	41.45
1	REAR BUMPER UNDER CVR RH	DEFORMED	108.00	108.00
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	532.00	-
1	EXHAUST MUFFLER	NOT NECESSARY	943.50	-
1	BOOTLID EMBLEM - HYBRID	NOT NECESSARY	24.30	-
1	BOOTLID EMBLEM - IONIQ	NOT NECESSARY	31.30	-
1	REAR FLOOR UNDER COVER	DEFORMED	225.00	225.00
1	SMART KEY ANTENNA	CRACKED	40.50	40.50
	LESS 20% DISCOUNT		-812.16	-407.10
			3,248.64	1,628.40
	NETT ITEMS			
1	BOOTLID COMFORTDELGRO (N)	NOT NECESSARY	35.00	-
1	BOOTLID 65521111 (N)	NOT NECESSARY	35.00	-
	BOOTLID APPS (N)	NOT NECESSARY	30.00	-
	REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-28.00	-18.00
			252.00	162.00

Report Ref No. NS/INC21001629/T1vf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	525.00
	SPRAYPAINT CHARGE.		900.00	500.00
	CHECK ALL LIGHTING.		60.00	30.00
	R/I REVERSE SENSOR.		120.00	30.00
	R/I EXHAUST MUFFLER.	NOT NECESSARY	100.00	-
	TOWING FEE.		-	-
			1,980.00	1,085.00
	GRAND TOTAL		5,480.64	2,875.40

RECOMMENDED COST OF REPAIRS (CONFIRMED)		2,875.40

Report Ref No. NS/INC21001629/T1vf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.