

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NTU	C INCOME INSUR	ANCE CO-OPERATIVE LTD	NS/INC21001629/T	1vf3e2		
189556			Date:	12-03-2021		
				INC4		
1.	Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SMU 9253M Veh. Inspected SHB 3298H					
	Insured Veh.	SMU 9253M			SHB 3298H	
	Policy No.	5118940832		age (\$)	0.00	
	Claim No.	MT/1119420-002	Exces		0.00	
	Assign From		Assign		02/02/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	C.C		1580	
	Engine No.	HIDDEN	Year o		2019	
	Chassis No.	KMHC851CVKU164449	Colou		YELLOW	
	Odometer	-	Steerii		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General GOOD					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST		6 mm	
	L/H Front Tyre	195/65 R15	WEST		6 mm	
	R/H Rear Tyre	195/65 R15	WEST		6 mm	
	L/H Rear Tyre	195/65 R15	WEST	_AKE	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	30/01/2021	Inspec	tion Date	02/02/2021	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					