

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3020G**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	41.00	-
1	HEADLAMP RH	CUT	1,388.00	1,388.00
1	FENDER RH	TO REPAIR SEE LABOUR	663.00	-
2	FRONT BUMPER SIDE RH / LH @\$14.30	NOT NECESSARY	28.60	-
2	FRONT BUMPER BRACKET LH / RH @\$24.60	NOT NECESSARY	49.20	-
1	FRONT BUMPER ASSY	DEFORMED	1,052.20	1,052.20
1	FRONT RAD GRILLE	CRACKED	1,480.00	1,110.10
	LESS 20% DISCOUNT		-940.40	-710.06
			3,761.60	2,840.24
	<b><u>NETT ITEMS</u></b>			
1	FRONT NUMBER W/HOLDER (N)	CRACKED	50.00	50.00
	LESS 10% DISCOUNT		-5.00	-5.00
			45.00	45.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BONNET HINGE RH AND FENDER RH.		720.00	420.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK WIRING.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
			1,440.00	950.00
	<b>GRAND TOTAL</b>		<b>5,246.60</b>	<b>3,835.24</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>3,000.00</b>

Report Ref No. NS/INC21001630/T1vf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.