

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21001631/EBS3Q2
Date: 25/03/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	XD5684M	Insured Vehicle No :	SLW2552Y
Date of Loss:	01/02/2021	Nature of Claim:	TP
			Claim No: MFL2021D0000600

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD5684M		
Make & Model:	MAN TGS 18.320, 10.5 D 4X2 BLS (M)	Engine No:	50530532693059
Reg. Date:	16/03/2012 (Man. Year: 2011)	Chassis No:	WMA06SZZ0CM588297
Colour:	Beige	Odometer:	48500 km
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	ANNAITE 4 mm	Rear Left Side:	ANNAITE 4 mm
Front Right Side:	ANNAITE 4 mm	Rear Right Side:	ANNAITE 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	668.50	601.65	66.85	10.00
Miscellaneous Items	0.00	0.00	0.00	0.00
Labour	400.00	250.00	150.00	37.50
Paintwork Labour	0.00	0.00	0.00	0.00
Towing	0.00	0.00	0.00	0.00
Gross Total (S\$)	1,068.50	851.65	216.85	20.29
+ GST 7.00/7.00% (S\$)	74.80	59.62	15.18	20.29
Nett Amount (S\$)	1,143.30	911.27	232.03	20.29
Global Sum Settlement (S\$)				0.00

INSPECTION

Date of Assignment:	03/02/2021		
Date Inspected:	05/02/2021	Inspected At:	Woodlands Transport Service Pte Ltd (HQ) 8 Gul Circle Singapore 629564
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Mar 2021)		
Parts:	N/A	MAN TGS 18.320 10.5 D 4X2 BLS (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for XD5684M)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHS CORNER LAMP	Broken	147.20 F	*147.20 FL
2	1		*FRONT LHS STEPWELL LOWER	Broken	521.30 F	*521.30 FL
F=Franchise part. L=ListItemDisc.				Sub Total (\$\$)	668.50	668.50
- List Item Discount on L Items 0.00/10.00% (\$\$)				0.00	66.85	
				Total Parts (\$\$)	668.50	601.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS AND REPLACE FRONT LHS STEP WELL LOWER AND CORNER LAMP	New	400.00	250.00
		Gross Labour Cost (S\$)	400.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >