

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

29/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP EQ

Xiao Chan

Accident date: 29/01/2021

Estimated repair cost for vehicle no: SJC446M HONDA STREAM 1.8 A '09

CHASSIS: RN61054047

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Cracked</i>		\$1,171.30	903
2	2	Rear Boot Lid Hinges <i>3 in</i>	\$68.10	\$136.20	+
3	2	Rear Boot Lid Shock Absorbers <i>3 in</i>	\$168.70	\$337.40	+
4	1	Rear Boot Lid Emblem Logo <i>Not in</i>		\$31.70	+
5	1	Rear Boot Lid Stream Logo <i>Not in</i>		\$36.80	+
6	1	Rear Boot Lid RSZ Logo <i>Not in</i>		\$43.60	+
7	1	Rear Boot Lid Center Moulding <i>Not in</i>		\$162.80	+
8	1	Rear Boot Lid Number Plate <i>Not in</i>		\$50.00	+
9	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$125.10	✓
10	1	Rear Boot Lid Inner Rubber <i>Not in</i>		\$122.50	✓
11	1	Rear Boot Lid Inner Trim Board <i>Cracked</i>		\$246.60	✓
12	1	Rear Windscreen Seal <i>Not in</i>		\$92.10	✓
13	2	Rear Tail Lamp <i>Not in</i>	\$362.50	\$725.00	✓
14	6	Rear Tail Lamp Clips <i>Not in</i>	\$8.00	\$48.00	20
15	1	Rear Bumper <i>Dented</i>		\$860.90	689
16	2	Rear Bumper Side Retainer <i>Not in</i>	\$38.40	\$76.80	✓
17	8	Rear Bumper Clips <i>Not in</i>	\$6.50	\$52.00	30
18	1	Rear Bumper Towing Cover <i>Dented</i>		\$34.70	✓
19	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00	200(SN)
20	1	Rear End Panel Outer <i>Dented</i>		\$360.90	✓
21	1	Rear End Panel Inner <i>Dented</i>		\$186.90	✓
22	1	Rear End Panel Top Garnish <i>Cracked</i>		\$147.90	✓
23	2	Rear Fender Inner Trim Board <i>Rt cracked</i>	\$385.30	\$770.60	285
24	1	Rear Floor Panel <i>Not in</i>		\$1,451.00	+
25	2	Rear Floor Panel Top Cover <i>2 Repainted</i>	\$166.00	\$332.00	+
26	1	Rear End Panel Outer <i>Repainted</i>		\$366.90	+
27	1	Rear End Panel Inner <i>Repainted</i>		\$205.90	+
28	1	Rear End Panel Top Garnish <i>Repainted</i>		\$147.90	+
29	1	Rear Floor Panel		\$1,451.00	+
30	2	Rear Floor Panel Top Cover	\$166.00	\$332.00	+

31	1	Rear Floor Panel Inner Trim Garnish	<i>Not m</i>	\$230.10	<i>x</i>
32	1	Rear Spare Tyre Lock	<i>Not m</i>	\$285.30	<i>x</i>
33	1	Rear Exhaust	<i>Not m</i>	\$524.20	<i>x</i>
34	1	Rear Center Exhaust	<i>Not m</i>	\$583.50	<i>x</i>
35	1	Rear Exhaust Chrome Pipe	<i>Not m</i>	\$158.00	<i>x</i>
36	2	Rear Exhaust Mounting	<i>Not m</i>	\$76.80	\$153.60 <i>x</i>

4125.50

3300.72 S.N: 200

Subtotal :- \$12,391.20

Labour charges

To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To remove & refit reverse camera	\$180.00	<i>x</i>
To remove & refit reverse sensor	\$100.00	<i>60</i>
To remove & refit rear & center exhaust	\$380.00	<i>x 80</i>
To check wiring	\$100.00	<i>30</i>
Tuff kote	\$150.00	<i>100</i>
Panel beating	\$1,600.00	<i>90</i>
Spray painting	\$1,600.00	<i>90</i>
Subtotal :-	<u>\$4,280.00</u>	

Total:- \$16,671.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5740.72

L/S: 4.6K

06 Days

4.6K