

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21001639/UPA3Q2
Date: 09/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100335662
Claimant Vehicle No :	SBT629H	Insured Vehicle No :	SKK6889A
Date of Loss:	02/02/2021	Nature of Claim:	TP
		Claim No:	5303390809SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBT629H		
Make & Model:	KIA CERATO, 1.6 SX (A)	Engine No:	G4FC8H222591
Reg. Date:	02/04/2009 (Man. Year: 2008)	Chassis No:	KNAFH221395023875
Colour:	Blue	Odometer:	193123 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,611.00	0.00	1,611.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	450.00	250.00	35.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,311.00	450.00	1,861.00	80.53
+ GST 7.00/7.00% (S\$)	161.77	31.50	130.27	80.53

Nett Amount (S\$)	2,472.77	481.50	1,991.27	80.53
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		603.50		

INSPECTION

Date of Assignment: 03/02/2021

Date Inspected: 03/02/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C	Repair	621.00 F	*- FL
2	1		*REAR BUMPER RETAINER LH	Not Necessary	24.00 F	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	304.00 F	*- FL
4	1		*REAR BUMPER CENTER LOWER GARNISH	Serviceable	102.00 F	*- FL
5	1		*SET REVERSE SENSOR	Serviceable	560.00 FS	*- FS
					Sub Total (\$\$)	1,611.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	1,611.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	350.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	300.00	250.00
3	ANTI-RUST COATING	New	50.00	0.00
Gross Labour Cost (\$\$)			700.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >