

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21001642/T1QD3E2

**Date:** 13/09/2021

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00139532005

**Claimant Vehicle No :** SMA5147T

**Insured Vehicle No :** SJK2456D

Date of Loss: 29/01/2021

Nature of Claim: TP

Claim No: SNM21D200571C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA5147T**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4433068

Reg. Date: 11/06/2018 (Man. Year: 2018)

Chassis No: RU11233065

Colour: Silver

Odometer: 47414 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,787.58	5,960.62	8,826.96	59.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,500.00	1,740.00	3,760.00	68.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,287.58</b>	<b>7,700.62</b>	<b>12,586.96</b>	<b>62.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,150.00</b>		
<b>(S\$)</b>	20,287.58	6,150.00	14,137.58	69.69
<b>+ GST 7.00/7.00% (S\$)</b>	1,420.13	430.50	989.63	69.69
<b>Nett Amount (S\$)</b>	<b>21,707.71</b>	<b>6,580.50</b>	<b>15,127.21</b>	<b>69.69</b>

### INSPECTION

Date of Assignment: 03/02/2021

Date Inspected: 03/02/2021 Inspected At:

56 Loyang Way # 04-04

Repairer: AP Automotive Services Pte Ltd

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2021)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMA5147T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cracked	1,796.50 FL	*1,796.50 FL
2	1		*HEADLAMP BRACKET RH	Cracked	50.70 FL	*50.70 FL
3	1		*FRONT BUMPER	Deformed	815.60 FL	*815.60 FL
4	1		*FRONT BUMPER RETAINER RH (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*FRONT BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*FRONT FENDER RH	Bent	379.75 FL	*379.75 FL
7	1		*FRONT FENDER COWLING RH	Torn	150.90 FL	*150.90 FL
8	1		*FRONT WHEEL ARC PROTECTOR RH	Cut	187.50 FL	*187.50 FL
9	1		*FRONT DOOR RH	Bent	1,208.55 FL	*1,208.55 FL
10	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	245.65 FL	*- FL
11	1		*FRONT DOOR INNER WINDOW MOULDING RH	Not Necessary	245.65 FL	*- FL
12	1		*FRONT DOOR WINDOW STICKER RH	Necessary	98.78 FL	*98.78 FL
13	1		*FRONT DOOR LOCK RH	Not Necessary	312.80 FL	*- FL
14	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	82.50 FL	*- FL
15	1		*FRONT DOOR INNER BOARD RH	Not Necessary	727.50 FL	*- FL
16	1		*FRONT DOOR WINDOW REGULATOR RH	Not Necessary	456.90 FL	*- FL
17	2		*FRONT DOOR HINGE UPPER & LOWER RH	Not Necessary	229.90 FL	*- FL
18	1		*FRONT DOOR CHECKER RH	Not Necessary	150.70 FL	*- FL
19	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	233.15 FL	*- FL
20	1		*FRONT DOOR INNER WEATHERSTRIP	Not Necessary	179.40 FL	*- FL
21	1		*FRONT DOOR STEP GARNISH RH	Not Necessary	291.70 FL	*- FL
22	1		*REAR DOOR RH	Repair	897.55 FL	*- FL
23	3		*REAR DOOR WEATHERSTRIP RH	Not Necessary	181.95 FL	*- FL
24	1		*REAR DOOR INNER WEATHERSTRIP	Not Necessary	107.85 FL	*- FL
25	1		*FRONT FENDER COWLING RH	Not Necessary	150.90 FL	*- FL
26	1		*REAR WHEEL ARC PROTECTOR RH	Cut	187.50 FL	*187.50 FL
27	1		*ROCKER PANEL RH	Repair	302.10 FL	*- FL
28	1		*REAR WHEEL ARC PROTECTOR RH	Repeated	187.50 FL	*- FL
29	1		*FRONT RIM RH	Cut	500.00 FS	*500.00 FS
30	1		*REAR RIM RH	Cut	500.00 FS	*500.00 FS
31	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
32	1		*FRONT FENDER COWLING CLIPS	Necessary	100.00 FS	*10.00 FS
33	1		*FRONT DOOR REFLECTIVE STICKER STRIP TOP }	Necessary	200.00 FS	*200.00 FS
34	1		*FRONT DOOR REFLECTIVE STICKER STRIP CENTER }		200.00 FS	*- FS
35	1		*FRONT DOOR REFLECTIVE STICKER STRIP BOTTOM }		200.00 FS	*- FS
36	1		*REAR DOOR REFLECTIVE STICKER STRIP TOP }		200.00 FS	*- FS
37	1		*REAR DOOR REFLECTIVE STICKER STRIP CENTER }		200.00 FS	*- FS
38	1		*REAR DOOR REFLECTIVE STICKER STRIP BOTTOM }		200.00 FS	*- FS
39	1		*ROCKER PANEL SEALANT	Not Necessary	200.00 FS	*- FS
40	1		*ROCKER PANEL STEP GARNISH RH	Deformed	2,500.00 FS	*800.00 FS
41	1		*FRONT WHEEL ARC PROTECTOR CLIPS	Necessary	100.00 FS	*10.00 FS
42	1		*REAR WHEEL ARC PROTECTOR CLIPS	Necessary	100.00 FS	*10.00 FS
43	1		*FRONT TYRE RH	Not Necessary	800.00 FS	*- FS
44	1		*REAR TYRE RH	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Sub Total (\$)</b>	<b>16,759.48</b>	<b>6,935.78</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,971.90	975.16
					<b>Total Parts (\$)</b>	<b>14,787.58</b>	<b>5,960.62</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	800.00
2	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	700.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	0.00
5	TO RNR FRONT DOOR SIDE MIRROR	New	250.00	0.00
6	TO RNR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
8	TO RNR UNDERCARRIAGE	New	250.00	0.00
9	TO CHECK WHEEL BALANCING	New	250.00	30.00
10	TO PERFORM RUST PROOFING	New	400.00	40.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
12	TO RNR FRONT AND DOOR MECHANISM	New	600.00	60.00
			<b>Gross Labour Cost (\$)</b>	<b>5,500.00</b>
				<b>1,740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >