

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001644/KVD3Q2

Date: 25/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00011462100
Claimant Vehicle No :	SLC409Y	Insured Vehicle No :	SMX3632B
Date of Loss:	29/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200645/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC409Y	Engine No:	CYR006983
Make & Model:	AUDI Q7, 2.0 TFSI QUATTRO (A)	Chassis No:	WAUZZZ4M7GD042809
Reg. Date:	28/04/2016 (Man. Year: 2016)	Odometer:	44539 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55R19	Rear Tyre Size:	255/55R19
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,863.26	6,636.14	2,227.12	25.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,560.00	1,450.00	48.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,873.26	8,196.14	3,677.12	30.97
Approved Total (Overridden) (\$\$)		6,550.00		
(\$\$)	11,873.26	6,550.00	5,323.26	44.83
+ GST 7.00/7.00% (\$\$)	831.13	458.50	372.63	44.83
Nett Amount (\$\$)	12,704.39	7,008.50	5,695.89	44.83

INSPECTION

Date of Assignment: 03/02/2021

Date Inspected: 04/02/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2021)
Parts:	M1-SUV	AUDI Q7 2.0 TFSI QUATTRO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC409Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (ALUMINIUM)	Dented	3,839.35 FL	*3,318.25 FL
2	1		*TAILGATE CENTER LOGO	Necessary	93.65 FL	*93.65 FL
3	1		*TAILGATE Q7 EMBLEM	Necessary	72.30 FL	*72.30 FL
4	1		*TAILGATE TFSI QUATTRO EMBLEM	Necessary	72.30 FL	*72.30 FL
5	1		*REAR END PANEL	Repair	487.15 FL	*- FL
6	1		*REAR BUMPER (UPPER)	Buckled	901.95 FL	*901.95 FL
7	1		*REAR BUMPER (LOWER)	Cracked	1,181.75 FL	*1,181.75 FL
8	1		*REAR BUMPER REINFORCEMENT	Repair	993.55 FL	*- FL
9	1		*REAR BUMPER SPONGE	Serviceable	102.00 FL	*- FL
10	1		*REAR BUMPER TOW COVER-LH	Dented	41.10 FL	*41.10 FL
11	1		*REAR BUMPER REFLECTOR-LH	Cracked	269.90 FL	*269.90 FL
12	2		*REAR BUMPER SENSOR	Scratched	417.70 FL	*417.70 FL
13	4		*REAR BUMPER SENSOR SEALS	Necessary	24.00 FL	*24.00 FL
14	1		*REAR BUMPER LOWER SPOILER	Cracked	853.65 FL	*853.65 FL
15	15		*REAR BUMPER CLIPS	Necessary	82.50 FL	*82.50 FL
16	1		*REAR EXHAUST END CHROME-LH	Serviceable	348.55 FL	*- FL
17	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,841.40	7,369.05
- List Item Discount on L Items 10.00/10.00% (\$\$)	978.14	732.91
Total Parts (\$\$)	8,863.26	6,636.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
2	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE	New	120.00	60.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	60.00
4	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
5	TO PANEL BEAT AND STRAIGHTEN REAR FLOORBOARD PANEL,REAR CHASSIS FRAME.TO CUT AND WELD REAR END PANEL.INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	1,200.00	500.00
6	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	800.00
7	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	160.00	0.00
Gross Labour Cost (S\$)			3,010.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >