

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001645/EVF3E2

Date: 09/03/2021

REFERENCE

Insured/Claimant:	CHUA PENG GEE	Policy No:	2070060616		
Date of Loss:	03/02/2021	Nature of Claim:	OD	Claim No:	6617577284SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT2410C		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGKH755885
Reg. Date:	02/04/2020 (Man. Year: 2019)	Chassis No:	KNAF3416ML5069636
Colour:	Red	Odometer:	8377 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$79,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,004.80	1,489.60	1,515.20	50.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,540.00	1,380.00	47.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,924.80	3,029.60	2,895.20	48.87
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,324.80	2,429.60	2,895.20	54.37
+ GST 7.00/7.00% (S\$)	372.74	170.07	202.67	54.37
Nett Amount (S\$)	5,697.54	2,599.67	3,097.87	54.37

INSPECTION

Date of Assignment:	03/02/2021		
Date Inspected:	03/02/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHF SPORT RIM - 16 S8004	Cut	480.00 FS	*480.00 FS
2	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
4	1		*GRILLE-FRONT BUMPER	Broken	262.00 FL	*262.00 FL
5	1		*BRACKET-FR BUMPER UPR SIDE MTG	Missing	22.00 FL	*22.00 FL
6	1		*MOULDING-FRONT BUMPER, RH	Cut	36.00 FL	*36.00 FL
7	1		*LAMP ASSY-SIDE REPEATER, RH	Cut	143.00 FL	*143.00 FL
8	1		*AIR DUCT-FR BUMPER, RH	Broken	14.00 FL	*14.00 FL
9	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
10	1		*GUARD ASSY-FRONT WHEEL, RH	Torn	95.00 FL	*95.00 FL
11	1		*LAMP ASSY-HEAD, RH	Not Necessary	1,219.00 FL	*- FL
12	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,631.00	1,737.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	626.20	247.40
Total Parts (\$\$)	3,004.80	1,489.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY FRT BUMPER & RHF FENDER	New	960.00	960.00
2	REMOVE / REFIT AC COND & RADIATOR	New	100.00	0.00
3	TOP UP AC GAS	New	80.00	0.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	RENEW RHF SPORT RIM - TRANSFER TYRE & WHEEL BALANCING	New	30.00	30.00
7	RENEW FRT BUMPER. REPAIR / ALIGN RHF FENDER	New	1,600.00	400.00
Gross Labour Cost (\$\$)			2,920.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >