

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001647/EVD3E2

Date: 24/02/2021

REFERENCE

Insured/Claimant:	TAN KIM SENG	Policy No:	2100444743		
Date of Loss:	03/02/2021	Nature of Claim:	OD	Claim No:	4218909702SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCP8001A		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGFH799594
Reg. Date:	05/01/2016 (Man. Year: 2015)	Chassis No:	KNAFZ411MF5534217
Colour:	White	Odometer:	110810 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$49,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,672.00	4,672.40	999.60	17.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	2,970.00	370.00	11.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,012.00	7,642.40	1,369.60	15.20
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	8,412.00	7,042.40	1,369.60	16.28
+ GST 7.00/7.00% (S\$)	588.84	492.97	95.87	16.28
Nett Amount (S\$)	9,000.84	7,535.37	1,465.47	16.28

INSPECTION

Date of Assignment:	03/02/2021		
Date Inspected:	03/02/2021	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*K3 SNOW WHITE PEARL SWP	Broken	1,044.00 FS	*1,044.00 FS
3	1		*BRACKET, IU ADHESIVE	Necessary	26.00 FS	*26.00 FS
4	1		*PANEL ASSY-HOOD	Dented	1,447.00 F	*1,447.00 FL
5	1		*LAMP ASSY-HEAD, RH	Broken	1,870.00 F	*1,870.00 FL
6	1		*MOULDING-FRONT BUMPER A/INTAKE	Not Necessary	104.00 F	*- FL
7	1		*GLASS-WINDSHIELD	Broken	1,099.00 F	*1,099.00 FL
8	1		*MOULDING-WINDSHIELD GLASS	Necessary	62.00 F	*62.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,672.00	5,568.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	895.60
Total Parts (S\$)	5,672.00	4,672.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT AIRDAM, BONNET, REPAIR FRT BUMPER, A-PILLAR RH	New	800.00	800.00
2	REMOVE & INSTALL FRT AIRDAM	New	100.00	80.00
3	RENEW FRT WINDSCREEN	New	240.00	240.00
4	APPLY SEALANT FOR FRT WINDSCREEN	New	80.00	80.00
5	RENEW FRT WINDSCREEN SOLAR FILM	New	220.00	220.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	SPRAY PAINT FOR FRT AIRDAM, FRT BUMPER, BONNET, FRT A-PILLAR RH, FRT FENDER RH	New	1,750.00	1,400.00
Gross Labour Cost (\$\$)			3,340.00	2,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >