

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Rea No . 10040-

CET DOG NO . MR-8500111-X

199405410K	ESTIMATE	GS1 REG NO : FIR-0300111			
Invoice Name & Address	Owner Name & Vehicle Info				
Tan Kim Seng BLK 111 TAMPINES ST 11 #10-219 SINGAPORE 521111	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No	/TAN KIM SENG SCP8001A / 05/01/201			
	Engline No	G4FGFH799594			
Contact No Mobile: 98346993	Make/Model	KIA/FORTE K3 1.6 A SX ADQ			
	Colour/Trim	SWP / WK			

Account No	Terms	Date/Time Printed	CSE	Operator	A common the design according to the last section of the section o	WIP No			
CSM00081	Cash	03/02/2021/ 14:37		442 / CocoLu		28532			
	Casii	Description of Good	s / Services		Qty	Unit Price	Disc%	An	ount
E PNT88000		BONNET, REPAIR FRT		PILLAR RH 1	X 490		e 	80	100.0
E PNT98000 SPRAY PAI	NT FOR F	FRT AIRDAM RT ¹ AIRDAM, FRT ¹ BUMPE	R, BONNET,	FRT A-PILLAR RH	351 X 4			149 g	1750.0
FRT FENDE E PNT88000 RENEW FRT		EEN					±≈¹ a		240.0 80.0
M SUNDRY APPLY SEA S SPECIALIST	LANT FOR	FRT WINDS TREEN	⇒ひ品	1500 G	· (2)	1			220.0
A 30000001			3 L I			j	5 3		30.0
10028901 TO CARRY (OUT DIAGN	CTRICAL SYSTEM OSTIC CHECK USING H	-SCAN PRO	TEST					120.
USING HI-S I SUNDRY						049			20.
BRACKET, 1	U AURESI	LSWP (Body Kil) - VE	- BR		1.00 1.00 1.00	1 000 .00 26.00 1447.00	00.00		1000.0 26.0 1447.0
PANEL ASSY LAMP ASSY- MOULDING-F	HEAD DH	PER A/INTAKE ? X	L/N		1.00	1870.00 104.00	00.00	_ :	1870. 104.
GLASS-WIND	SHIFFD	GLASS - MC		Sten CLKK) OD MAL	1.00	1099.00 62.00			62.0
ger combination with the desired		and a set if i		Excess -1					
LKK Auto Co the Repairer • To resurvey b	of the follo efore/after sp	wing:		P/POL SM			e		2
Confirm & acc	urvey is on a odification(s) is	Williout Frejo		3/2/21, 2.30	か 7% GST on	Nett 8968.00			968.0 627.7
Supplementi is subject to Acknowledge.	final approval	from Insurance pany		s ags		al Payable			595.7
3		and company stamp							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.