

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG21001651/EQD3E2

**Date:** 19/03/2021

### REFERENCE

Insured/Claimant:	YUEN HO TIAN	Policy No:	1900017477		
Date of Loss:	03/02/2021	Nature of Claim:	OD	Claim No:	4079072459SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ6305A		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UHN8611
Reg. Date:	14/03/2019 (Man. Year: 2018)	Chassis No:	MMBSTA13AKH001202
Colour:	Silver	Odometer:	28653 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,724.72	4,455.02	1,269.70	22.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,790.00	5,260.00	2,530.00	32.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,514.72</b>	<b>9,715.02</b>	<b>3,799.70</b>	<b>28.12</b>
<b>+ GST 7.00/7.00% (S\$)</b>	946.03	680.05	265.98	28.12
<b>Nett Amount (S\$)</b>	<b>14,460.75</b>	<b>10,395.07</b>	<b>4,065.68</b>	<b>28.12</b>

### INSPECTION

Date of Assignment:	03/02/2021	
Date Inspected:	03/02/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*FLOOR, RR	Not Necessary	956.00 FL	*- FL
3	1		*PANEL, RR END	Dented	427.00 FL	*427.00 FL
4	1		*BOARD, TRUNK ROOM FLOOR	Broken	195.00 FL	*195.00 FL
5	1		*TRIM, RR END	Crushed	66.00 FL	*66.00 FL
6	1		*ANT, KEYLESS OPERATION, RR	Broken	96.00 FL	*96.00 FL
7	1		*BUZZER, KEYLESS OPERATIO, RR	Not Necessary	91.00 FL	*- FL
8	1		*STRIKER, TRUNK LID LATCH	Not Necessary	20.00 FL	*- FL
9	1		*STRIKER, TRUNK LID LATCH	Not Necessary	20.00 FL	*- FL
10	1		*WEATHERSTRIP, TRUNK LID	Crushed	157.00 FL	*157.00 FL
11	1		*PANEL, TRUNK LID	Dented	795.00 FL	*795.00 FL
12	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
13	1		*GARNISH, RR END PANEL	Not Necessary	336.00 FL	*- FL
14	1		*LAMP ASSY, COMB, RR LH	Broken	337.00 FL	*337.00 FL
15	1		*LAMP ASSY, COMB, RR RH	Broken	337.00 FL	*337.00 FL
16	1		*REFLECTOR LH	Not Necessary	23.00 FL	*- FL
17	1		*REFLECTOR RH	Not Necessary	23.00 FL	*- FL
18	1		*LAMP ASSY, LICENSE PLATE	Not Necessary	51.00 FL	*- FL
19	1		*LAMP ASSY, LICENSE PLATE	Not Necessary	51.00 FL	*- FL
20	1		*DUCT, RR VENTILATOR	Not Necessary	30.00 FL	*- FL
21	1		*COVER, RR VENTILATOR	Crushed	40.00 FL	*40.00 FL
22	3		*CLIP, GEARSHIFT CONTROL LIN	Not Necessary	9.00 FL	*- FL
23	1		*BRACKET, RR BUMPER, LH	Broken	28.00 FL	*28.00 FL
24	1		*BRACKET, RR BUMPER, RH	Broken	28.00 FL	*28.00 FL
25	6		*CLIP, FR BUMPER	Necessary	24.00 FL	*24.00 FL
26	1		*FACE, RR BUMPER	Dented	751.00 FL	*751.00 FL
27	1		*ATTRAGE BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
28	4		*GROMMET	Necessary	12.00 FL	*12.00 FL
29	4		*CLIPS	Necessary	12.00 FL	*12.00 FL
30	1		*LATCH,TRUNK LID	Bent	218.00 FL	*218.00 FL
31	1		*MARK,THREE-DIAMOND	Necessary	70.00 FL	*70.00 FL
32	4		*GROMMET	Necessary	12.00 FL	*12.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,929.00	5,289.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,204.28	833.98
Total Parts (\$\$)	5,724.72	4,455.02

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR SPOILER LIP, REAR BUMPER, REAR BODY KITS. CUT/WELD REAR FLOOR PANEL, REAR END PANEL. REPAIR RH REAR FENDER, REPAIR LH REAR FENDER	New	3,150.00	2,250.00
2	REMOVE & INSTALL REAR CABIN TO FACILITATE REPAIR WORK	New	120.00	120.00
3	REMOVE & INSTALL PARKING ASSIST	New	60.00	60.00
4	TO REMOVE AND INSTALL REAR BODY KITS AND REAR SPOILER LIP	New	160.00	160.00
5	PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR BOOT LID, REAR SPOILER, REAR BUMPER, REAR BODY KITS, RH REAR FENDER, LH REAR FENDER AND AFFECTED PORTION	New	3,150.00	2,100.00
6	PERFORM RUST PREVENTION	New	120.00	40.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	APPLY BODY SEALANT	New	120.00	120.00
9	SUPPLY C&C LOGO	New	40.00	40.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	SUPPLY REAR PARKING SENSOR	New	220.00	220.00
12	SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	0.00
13	REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK	New	450.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,790.00</b>	<b>5,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >