

ASS. REC. BY: Tan JkhREF: CS/CT/2/00/652/T1q d3.

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. DMPCSNW00054812000Claims No. SNM21D200646C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 882K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMN/217H Yr Regn: 249, JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: Red A/C: Insured / Std / NI / NASp. Reading: 69907 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: R411316792Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 9/2/21Survey held at Tan LimDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFrt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/02/21 @ 11.46am revised to Adeline Chng via Merimen.

24/05/21 @ 3.09pm checked with William, the vehicle has not send in for repair.

24/05/21 Submit Preli. Report.

Date/Time, File Pass to?



Preli. Report

1) 25/05 Typist



Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Rep. Format: \_\_\_\_\_

Lump Sum / L.B. (\$) \_\_\_\_\_

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\_\_\_\_ S + RS \_\_\_\_ SI

Photos

Others

TOTAL



陳林摩喀私人有限公司  
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : SJH8057Z

Date of Accident : 01 February 2021

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Mr Png Boon Leng

Date : 02 February 2021

*LKK - Tan Lim*

Estimate To Repair SMN1217H - Honda VEZEL 1.5X CVT

Chassis No : RU11316792

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	o/s headlamp	\$ 1,921.80 x NN
02	1 pc	o/s headlamp lower bracket	\$ 54.50 x NN
03	1 pc	front bumper	\$ 863.50 <i>de</i>
04	1 pc	front bumper reinforcement	\$ 313.50 x NN
05	1 pc	front bumper side retainer o/s	\$ 19.80 x NN
06	12 ps	front bumper clips @ \$3.90	\$ 46.80 <i>de</i>
07	1 pc	front bumper tow cover	\$ 28.10 x NN
08	1 pc	front bumper lower spoiler	\$ 224.30 x NN
09	1 pc	radiator grille	\$ 289.60 x NN
		Less 20 %	\$ 3,761.90
			\$ 752.38
			\$ 3,009.52
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 50.00 <i>30</i>
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00 <i>200</i>
03		Putty and spray painting of the affected portion.	\$ 600.00 <i>200</i>
			\$ 1,250.00
		Total	\$ 4,259.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Tan Lim 97495749*  
*9/2/21 @ 1050*

*2 days*

*tanlim@klkauto.com*

*Resurvey before paint*