

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18007427/NES3Q2-1

Date: 19/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHC6794S	Insured Vehicle No :	SH6314M
Date of Loss: 19/04/2018	Nature of Claim: TP	Claim No: MCT18040533

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6794S		
Make & Model:	HYUNDAI I30 (FD), 1.6 DOHC (A)	Engine No:	D4FBGZ144458
Reg. Date:	13/09/2017 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ134083
Colour:	Silver	Odometer:	70383 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,387.99	656.60	731.39	52.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	950.00	550.00	36.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,887.99	1,606.60	1,281.39	44.37
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	2,887.99	1,250.00	1,637.99	56.72
+ GST 7.00/7.00% (S\$)	202.16	87.50	114.66	56.72
Nett Amount (S\$)	3,090.15	1,337.50	1,752.65	56.72
+ Loss of Use (4.5 x S\$40.00/day) (S\$)		180.00		
+ Car Rental (4.5 x S\$109.94/day) (S\$)		494.73		
(S\$)		2,012.23		
Liabile Amount (50.00%) (S\$)		1,006.12		
Global Sum Settlement (S\$)		1,000.00		

INSPECTION

Date of Assignment: 20/04/2018

Date Inspected: 20/04/2018 Inspected At:

Premier Automotive Services Pte Ltd
(HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2018)
Parts:	144	HYUNDAI I30 (FD) 1.6 DOHC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC6794S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S FENDER	Dented	514.02 FL	*514.02 FL
2	1		*FRONT O/S FENDER INNER SHIELD	Torn	176.72 FL	*176.72 FL
3	1		*FRONT BUMPER	Repair	811.11 FL	*- FL
4	1		*FRONT BUMPER O/S SIDE BRACKET	Cracked	32.51 FL	*32.51 FL
5	1		*SET FRONT BUMPER CLIPS	Not Necessary	52.50 FS	*- FS
6	1		*FRONT O/S FENDER STICKER	Necessary	30.00 FS	*30.00 FS
7	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Necessary	28.00 FS	*28.00 FS
8	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,694.86	801.25
- List Item Discount on L Items 20.00/20.00% (\$\$)	306.87	144.65
Total Parts (\$\$)	1,387.99	656.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WHEEL ALIGNMENT	New	80.00	0.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK-OUT,STRAIGHTEN ,REPAIR,RESHAPE OF THE FRONT O/S DOOR	New	700.00	500.00
3	TO PUTTY AND SPRAY PAINTING ON THE FRONT BUMPER ,FRONT O/S FENDER ,FRONT O/S DOOR	New	600.00	400.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND RPELACED PANELS	New	120.00	50.00
Gross Labour Cost (\$\$)			1,500.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >