

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21001658/ABA3Q2
Date: 23/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070106066
Claimant Vehicle No :	SLT6398R	Insured Vehicle No :	SFY6228T
Date of Loss:	22/01/2021	Nature of Claim:	TP
		Claim No:	8534910394SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6398R	Engine No:	LEB5955343
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31255326
Reg. Date:	03/11/2017 (Man. Year: 2017)	Odometer:	54520 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,303.04	962.64	1,340.40	58.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	600.00	700.00	53.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,603.04	1,562.64	2,040.40	56.63
Approved Total (Overridden) (S\$)		1,200.00		

Adjuster Report

(S\$)	3,603.04	1,200.00	2,403.04	66.69
+ GST 7.00/7.00% (S\$)	252.21	84.00	168.21	66.69
Nett Amount (S\$)	3,855.25	1,284.00	2,571.25	66.69
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,686.00		
Global Sum Settlement (S\$)		1,550.00		

INSPECTION

Date of Assignment: 03/02/2021

Date Inspected: 03/02/2021

Estimated Period of Repair: 3.0 days

Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	897.50 FL	*897.50 FL
2	1		*REAR END PANEL	Not Necessary	411.90 FL	*- FL
3	2		*REAR BUMPER BRACKET L/R	Not Necessary	78.40 FL	*- FL
4	2		*REAR BUMPER SIDE HOLDER L/R	Necessary	55.80 FL	*55.80 FL
5	1		*REAR BOOT LID	Repair	997.70 FL	*- FL
6	1		*SET REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,791.30	1,153.30
- List Item Discount on L Items 20.00/20.00% (\$)	488.26	190.66
Total Parts (\$)	2,303.04	962.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	700.00	200.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	600.00	400.00
Gross Labour Cost (S\$)			1,300.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >