

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS3/AGI21001667/Eqd3e2
		INSURANCE) 190 ENUE #03-01 SINGAPORE RESINGAPORE 239924	Date	22/02/2021
			Code	: AGI
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	SLF 1282Y	Veh. Inspected	SKE 3507D
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10008561/KY	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	04/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	MR053BK4107057659	Colour	GREY
	Odometer	301453 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	FIRENZA	4 mm
	L/H Front Tyre	215/60 R16	FIRENZA	4 mm
	R/H Rear Tyre	215/60 R16	FIRENZA	4 mm
	L/H Rear Tyre	215/60 R16	FIRENZA	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.			
5.	General Information			
	Accident Date	01/01/2021	Inspect Date / Time	05/02/2021 ( 10:30 AM )
	Survey held at	K'S PERFORMANCE		
	67 YUNNAN DRIVE 3 SINGAPORE 637954			
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b.	Estimate Days of Repair			
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days		

Report Ref No. CS3/AGI21001667/Eqd3e2

Inspected By

**CHEN TSUE YEE** 

**Automotive Assessor** 

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**