



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YVONNE			Ref: CC4/ASM21001669/Qba3q2 Date: 05/08/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SKC 6639Y	Veh. Inspected	SLB 188P
	Policy No.	GA462186	Coverage (\$)	0.00
	Claim No.	S1M031Z1	Excess (\$)	0.00
	Assign From		Assign Date	04/02/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	VOLVO XC90 T5	c.c	1969
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	YV1LF10ACH1109892	Colour	GOLD
	Odometer	80228 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	MICHELIN	6 mm
	L/H Front Tyre	235/55 R19	MICHELIN	6 mm
	R/H Rear Tyre	235/55 R19	MICHELIN	6 mm
	L/H Rear Tyre	235/55 R19	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	01/02/2021	Inspection Date	24/03/2021
	Survey held at	CAR PRO AUTO 399J WOODLANDS ROAD SINGAPORE 678008		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	