

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21001670/AGQD3E2

**Date:** 13/07/2021

### REFERENCE

|                              |                                      |                             |            |
|------------------------------|--------------------------------------|-----------------------------|------------|
| Handling Insurer:            | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | 1001434008 |
| <b>Claimant Vehicle No :</b> | SMV1517A                             | <b>Insured Vehicle No :</b> | YN3882G    |
| Date of Loss:                | 01/02/2021                           | Nature of Claim:            | TP         |
|                              |                                      | Claim No:                   | 252886     |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                        |             |                   |
|-----------------------------|----------------------------------------|-------------|-------------------|
| Reg No:                     | SMV1517A                               | Engine No:  | 1ZR0F35889        |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 Elegance (A) | Chassis No: | MR2BE3BE700009243 |
| Reg. Date:                  | 18/09/2020 (Man. Year: 2020)           | Odometer:   | 3771 km           |
| Colour:                     | Silver                                 |             |                   |
| Engine Capacity:            | 1598 cc                                |             |                   |
| Market Value/New Car Price: | N/A                                    |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price             |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/45 R17    | Rear Tyre Size:  | 225/45 R17    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                    | 14,546.82        | 6,128.55        | 8,418.27         | 57.87        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 5,700.00         | 2,710.00        | 2,990.00         | 52.46        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>20,246.82</b> | <b>8,838.55</b> | <b>11,408.27</b> | <b>56.35</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>6,800.00</b> |                  |              |
| <b>(S\$)</b>                             | 20,246.82        | 6,800.00        | 13,446.82        | 66.41        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,417.28         | 476.00          | 941.28           | 66.41        |
| <b>Nett Amount (S\$)</b>                 | <b>21,664.10</b> | <b>7,276.00</b> | <b>14,388.10</b> | <b>66.41</b> |

### INSPECTION

|                             |            |               |                                                                            |
|-----------------------------|------------|---------------|----------------------------------------------------------------------------|
| Date of Assignment:         | 04/02/2021 |               |                                                                            |
| Date Inspected:             | 04/02/2021 | Inspected At: | Stk Auto (s) Pte Ltd (HQ)<br>8 kaki bukit ave4, #03-21<br>Singapore 415875 |
| Estimated Period of Repair: | 9.0 days   |               |                                                                            |

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                         |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 18 Jun 2021)                           |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 Elegance (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMV1517A)                                                                                                                                    |                                                                         |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                         |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                         |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *BOOT LID                          | Distorted     | 956.40 FL   | *956.40 FL   |
| 2   | 1   |          | *BOOT LID WEATHERSTRIP             | Cut           | 270.60 FL   | *270.60 FL   |
| 3   | 1   |          | *BOOT LID HINGE RH                 | Bent          | 167.40 FL   | *167.40 FL   |
| 4   | 1   |          | *BOOT LID HINGE LH                 | Bent          | 167.40 FL   | *167.40 FL   |
| 5   | 1   |          | *BOOT LID LOCK                     | Damaged       | 550.60 FL   | *285.00 FL   |
| 6   | 1   |          | *BOOT LID CHROME                   | Not Necessary | 207.70 FL   | *- FL        |
| 7   | 1   |          | *BOOT LID REFLECTOR RH             | Cracked       | 729.20 FL   | *355.00 FL   |
| 8   | 1   |          | *BOOT LID REFLECTOR LOWER CHROME   | Cracked       | 125.00 FL   | *125.00 FL   |
| 9   | 1   |          | *BOOT LID EMBLEM COROLLA           | Necessary     | 65.00 FL    | *65.00 FL    |
| 10  | 1   |          | *BOOT LID EMBLEM ALTIS             | Necessary     | 65.00 FL    | *65.00 FL    |
| 11  | 1   |          | *BOOTLID INNER TRIMBOARD           | Not Necessary | 359.20 FL   | *- FL        |
| 12  | 1   |          | *BOOT LID LOGO                     | Necessary     | 95.60 FL    | *95.60 FL    |
| 13  | 1   |          | *BOOTLID GLASS                     | Not Necessary | 1,534.90 FL | *- FL        |
| 14  | 1   |          | *BOOT LID REFLECTOR LH             | Cut           | 729.20 FL   | *355.00 FL   |
| 15  | 1   |          | *BOOT LID REFLECTOR CHROME LH      | Not Necessary | 125.00 FL   | *- FL        |
| 16  | 1   |          | *REAR BUMPER                       | Distorted     | 560.10 FL   | *560.10 FL   |
| 17  | 1   |          | *REAR BUMPER RETAINER RH           | Necessary     | 150.40 FL   | *58.00 FL    |
| 18  | 1   |          | *REAR BUMPER RETAINER LH           | Not Necessary | 150.40 FL   | *- FL        |
| 19  | 1   |          | *REAR BUMPER TOWING COVER          | Deformed      | 25.00 FL    | *25.00 FL    |
| 20  | 1   |          | *REAR BUMPER REINFORCEMENT         | Bent          | 780.60 FL   | *345.00 FL   |
| 21  | 1   |          | *REAR END PANEL                    | Distorted     | 616.20 FL   | *616.20 FL   |
| 22  | 1   |          | *REAR END PANEL TOP GARNISH        | Deformed      | 650.60 FL   | *165.00 FL   |
| 23  | 1   |          | *RH REAR FENDER                    | Distorted     | 1,085.90 FL | *1,085.90 FL |
| 24  | 1   |          | *RH REAR FENDER INNER SHIELD       | Not Necessary | 350.60 FL   | *- FL        |
| 25  | 1   |          | *LH REAR FENDER                    | Repair        | 1,085.90 FL | *- FL        |
| 26  | 1   |          | *SPARE TYRE PANEL                  | Repair        | 1,250.00 FL | *- FL        |
| 27  | 1   |          | *RH TAILLAMP                       | Smashed       | 1,560.70 FL | *980.00 FL   |
| 28  | 1   |          | *RH TAILLAMP INNER PANEL           | Distorted     | 108.80 FL   | *108.80 FL   |
| 29  | 1   |          | *LH TAILLAMP                       | Cracked       | 1,560.70 FL | *980.00 FL   |
| 30  | 1   |          | *RH TAILLAMP INNER GARNISH         | Cut           | 45.00 FL    | *20.00 FL    |
| 31  | 10  |          | *REAR BUMPER CLIPS                 | Necessary     | 50.00 FS    | *30.00 FS    |
| 32  | 10  |          | *REAR END PANEL TOP GARNISH CLIPS  | Necessary     | 50.00 FS    | *10.00 FS    |
| 33  | 10  |          | *RH REAR FENDER INNER SHIELD CLIPS | Not Necessary | 50.00 FS    | *- FS        |
| 34  | 1   |          | *RH REAR SPORT RIM                 | Not Necessary | 450.00 FS   | *- FS        |
| 35  | 1   |          | *REAR BUMPER REVERSE SENSOR        | Damaged       | 650.00 FS   | *200.00 FS   |
| 36  | 1   |          | *LH REAR SPORT RIM                 | Not Necessary | 1,200.00 FS | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>18,579.10</b> | <b>8,091.40</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 4,032.28         | 1,962.85        |
| <b>Total Parts (\$\$)</b>                                  | <b>14,546.82</b> | <b>6,128.55</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                |          |                 |                 |
| 1                               | TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS    | New      | 2,500.00        | 1,200.00        |
| 2                               | TO SPRAY PAINT ON ACCIDENT AREAS               | New      | 2,500.00        | 1,150.00        |
| 3                               | TO REMOVE AND REFIT REAR WINDSCREEN            | New      | 150.00          | 120.00          |
| 4                               | TO CONDUCT WIRING AND REMOVE AND REFIT REVERSE | New      | 100.00          | 50.00           |
| 5                               | TO REMOVE AND REFIT BOOT LID COMPARTMENT       | New      | 150.00          | 60.00           |
| 6                               | TO CHECKING WIRING AND TEST TAILLAMP           | New      | 150.00          | 30.00           |
| 7                               | TO RUST PROOFING ACCIDENT AREAS                | New      | 150.00          | 100.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                |          | <b>5,700.00</b> | <b>2,710.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >