

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyo

Date: 07 Jun 2021

Preliminary Advice

Insured Vehicle No	: YN3882G	Accident Date	: 01/02/2021
TP Vehicle No	: SMV1517A	Assignment Date	: 04/02/2021
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 9
Date of Inspection	: 04/02/2021		
Inspection At	: STK AUTO (S) PTE LTD (HQ) 8 KAKI BUKIT AVE4, #03-21 SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,246.83
Revised Amount	:S\$	8,817.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,817.25

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis.