

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001679/T1QF3Q2
Date: 19/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNW00122852002	
Claimant Vehicle No : SJM7536M	Insured Vehicle No : GBH334X	
Date of Loss: 02/02/2021	Nature of Claim: TP	Claim No: SNM21D200658/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM7536M		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4820457
Reg. Date:	15/01/2009 (Man. Year: 2008)	Chassis No:	MR053ZEE106126328
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,884.57	2,121.42	2,763.15	56.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,230.00	550.00	30.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,664.57	3,351.42	3,313.15	49.71
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	6,664.57	2,700.00	3,964.57	59.49

INSPECTION

Date of Assignment:	04/02/2021	
Date Inspected:	04/02/2021 Inspected At:	Huat Hock Motor Workshop (HQ) BLK 3012 BEDOK NORTH AVE 4, #01-2054 BEDOK INDUSTRIAL PARK E Singapore 1648
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

3/19/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Mar 2021)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SJM7536M)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	465.10 F	*465.10 FL
2	1		*FRONT BUMPER SIDE RETAINER	Deformed	65.30 F	*65.30 FL
3	1		*FRONT BUMPER BEAM	Bent	358.70 F	*358.70 FL
4	1		*FRONT BUMPER CLIP	Necessary	38.00 F	*38.00 FL
5	1		*FRONT BUMPER FOG LAMP	Cracked	201.40 F	*201.40 FL
6	1		*FRONT BUMPER FOG LAMP COVER	Dented	161.41 F	*161.41 FL
7	1		*FRONT BUMPER LOWER LIP	Deformed	280.00 F	*280.00 FL
8	1		*FRONT LH FENDER	Bent	415.30 F	*415.30 FL
9	1		*FRONT LH FENDER LOGO (VVTI)	Necessary	41.90 F	*41.90 FL
10	1		*FRONT LH FENDER INNER SHIELD	Deformed	124.30 F	*124.30 FL
11	1		*FRONT LH FENDER INNER SHIELD CLIP	Necessary	38.00 F	*38.00 FL
12	1		*FRONT HEADLAMP LH	Cracked	459.15 F	*459.15 FL
13	1		*FRONT BONNET	Repair	840.90 F	*- FL
14	1		*FRONT BONNET RUBBER	Not Necessary	110.35 F	*- FL
15	1		*FRONT BONNET INSULATOR	Not Necessary	219.40 F	*- FL
16	1		*FRONT BONNET INSULATOR CLIP	Not Necessary	30.00 F	*- FL
17	1		*FRONT SUPPORT PANEL	Repair	715.11 F	*- FL
18	1		*FRONT BUMPER TOP RUBBER	Not Necessary	75.15 F	*- FL
19	1		*WIPER TANK & MOTOR	Deformed	245.10 F	*180.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,884.57	2,828.56
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	707.14
Total Parts (S\$)	4,884.57	2,121.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	800.00	600.00
2	TO SPRAY PAINTING ON AFFECTED AREA.BONNET,BUMPER & FENDER	New	800.00	600.00
3	TO CHECK ON ELECTRICAL WIRING SYSTEM & HEADLAMP FOCUS	New	60.00	30.00
4	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			1,780.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >