

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Tan Kok Hui

Our ref. : UAM20.08.17-AK-STP-RCG-SFA7333S

Date : 14 Sep 2020

REFERENCE

Assign by	: Tan Kok Hui	Insured	: To be advice
Assign on	: 27 Aug 2020	Policy no.	: To be advice
Inspection on	: 27 Aug 2020	Claim no.	: To be advice
Accident on	: 24 Aug 2020	Sum insured	: To be advice
Workshop name	: Revol Carz Garage Pte Ltd	Excess	: Not applicable
Inspection at	: 10, Ang Mo Kio Ind. Park 2A #02-18 AMK Autopoint Singapore 568047	3rd party Veh.	: To be advice
		3rd party ins.	: To be advice

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SFA7333S	Odometer	: 124475 km
Make / Model	: BMW 640I A	Chassis no.	: WBALW72000C582730
Regn. date	: 05 Aug 2011	Engine no.	: 15257765N55B30A
Body colour	: Black	Engine cap.	: 2979 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good


TYRE CONDITION ON VEHICLE

	Make	Size	Tread depth	Type of road wheel
Front N/S	: Michelin	245/35ZR19	70%	Alloy
Front O/S	: Michelin	245/35ZR19	70%	Alloy
Rear N/S	: Michelin	275/30ZR19	70%	Alloy
Rear O/S	: Michelin	275/30ZR19	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT

<p>On the rear in the direction from rear to front.</p>	
---	--

SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

The impact of the collision has damaged / affected the bootlid, rear bumper, rear end panel, taillamps, fault code and etc...

Please refer to Annex A (Appraisalment Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 28 Aug 2020 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Revol Carz Garage Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 14,150.00 to carry out the repairs. Please refer to Annex A (Appraisalment Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 10 (Ten) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,
United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SFA7333S

Our reference : UAM20.08.17-AK-STP-RCG-SFA7333S

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
<u>LIST ITEMS</u>					
1	1	Bootlid	Dented	2238.20	2238.20
2	1	Bootlid emblem "640I"	Necessary	74.10	74.10
3	1	Bootlid lock lever with logo	Jammed	271.25	271.25
4	2	Bootlid reflector @ SGD 468.10	Cracked	936.20	936.20
5	1	Bootlid 3rd brake light	Cracked	452.60	452.60
6	1	Bootlid inner trim	Wrinkled	325.40	325.40
7	1	Bootlid inner lock assy	Shorted	669.75	669.75
8	1	Bootlid weatherstrip	Necessary	184.50	184.50
9	2	Bootlid hydraulic damper @ SGD 176.00	Bend	352.00	352.00
10	2	Taillamp @ SGD 751.50	Cracked	1503.00	1503.00
11	2	Taillamp garnish @ SGD 96.40	Deformed	192.80	192.80
12	2	Taillamp lower bracket @ SGD 112.00	Distorted	224.00	224.00
13	1	Rear bumper	Deformed	1578.90	1578.90
14	2	Rear bumper side retainer @ SGD 182.90	Distorted	365.80	365.80
15	2	Rear bumper bracket @ SGD 238.20	Distorted	476.40	476.40
16	1	Rear bumper carrier	Cracked	182.45	182.45
17	1	Rear bumper inner base	Cracked	238.50	238.50
18	1	Rear bumper lower cover	Cracked	275.40	275.40
19	2	Rear bumper reflector @ SGD 67.10	O/S Cracked	134.20	67.10
20	1	Rear bumper reinforcement	Bend	632.10	632.10
21	4	Rear PDC sensor @ SGD 256.85	Shorted	1027.40	1027.40
22	4	Sensor holder @ SGD 49.50	Necessary	198.00	198.00
23	2	Rear number plate lamp @ SGD 124.20	Cracked	248.40	248.40
24	1	Rear end panel	Dented	845.50	845.50
25	1	Rear end panel top garnish	Cracked	260.10	260.10
26	2	Rear fender	Refer To Labour	0.00	0.00
27	2	Rear fender inner trim @ SGD 551.70	O/S Torn	903.40	551.70
28	2	Active head restraint repair kit @ SGD 280.00	Activated/Necessary	560.00	560.00
29	1	Convertible bootlid antenna amplifier (6957348-01)	Shorted	205.50	205.50
30	1	Multi-band GPS antenna module (6957347-01)	Shorted	205.50	205.50
31	1	Rear diversity antenna aerial amplifier (9206681-02)	Shorted	195.00	195.00
				15956.35	15537.55
Less 0% / 10%				0.00	1553.76
				15956.35	13983.80

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SFA7333S

Our reference : UAM20.08.17-AK-STP-RCG-SFA7333S

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Balance C/F	15956.35	13983.80
<u>SPECIAL NETT ITEMS</u>					
1	1	Sundries	Necessary	50.00	30.00
2	1	Rear number plate with casing	Bend	80.00	60.00
3	1	Bootlid sealant	Necessary	100.00	80.00
4	1set	Bootlid inner trim clips	Necessary	25.00	25.00
5	2set	Bootlid reflector clips @ SGD 25.00	Necessary	50.00	50.00
6	2	Bootlid reflector seal @ SGD 30.00	Necessary	60.00	50.00
7	1set	Rear bumper clips	Necessary	80.00	80.00
8	1set	Taillamp clips o/s	Necessary	30.00	30.00
9	1	Taillamp seal o/s	Necessary	30.00	25.00
10	1set	Rear end panel top garnish clips	Necessary	30.00	30.00
11	1	Rear end panel sealant	Necessary	100.00	80.00
12	2set	Rear fender inner trim clips @ SGD 45.00	Necessary	90.00	90.00
				<u>725.00</u>	<u>630.00</u>
TOTAL				16681.35	14613.80

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SFA7333S

Our reference : UAM20.08.17-AK-STP-RCG-SFA7333S

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Balance C/F	16681.35	14613.80
<u>LABOUR & MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.		1400.00	1200.00
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	60.00
3		To remove and refit interior upholstery to facilitate the repair.		200.00	180.00
4		To remove and refit bootlid component to replace bootlid, check and re-adjust the close gap and alignment and water seepage.		100.00	80.00
5		To remove and refit both front seat headrest including reset ECU fault and program.		450.00	380.00
6		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	180.00
7		Supply spray paint material and necessary items to respray bootlid, rear bumper, rear end panel, rear fenders and other affected area / panels.		1200.00	1000.00
TOTAL				3630.00	3080.00
Total Parts and Labour Cost of Repair				20311.35	17693.80
Less (Lumpsum repair adjustment)					3543.80
Adjustment Parts and Labour Cost of Repair					14150.00

