

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21001688/EVF3E2

Date: 05/03/2021

REFERENCE

Insured/Claimant: CHIA SZE LEA, DESMOND

Policy No:

Date of Loss: 03/02/2021

Nature of Claim: OD Claim No: 9990170716SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK5990Y**

Make & Model: KIA CERATO, 1.6 (A)

Engine No: G4FGJH720081

Reg. Date: 17/04/2019 (Man. Year: 2018)

Chassis No: KNAF3416MK5036779

Colour: White

Odometer: 32162 km

Engine Capacity: 1591 cc

Market Value/New Car Price: S\$74,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: NFERA 5 mm

Rear Left Side: NFERA 5 mm

Front Right Side: NFERA 5 mm

Rear Right Side: NFERA 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,146.02	5,897.60	1,248.42	17.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,520.00	3,810.00	1,710.00	30.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,666.02	9,707.60	2,958.42	23.36
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,066.02	9,107.60	2,958.42	24.52
+ GST 7.00/7.00% (S\$)	844.62	637.53	207.09	24.52
Nett Amount (S\$)	12,910.64	9,745.13	3,165.51	24.52

INSPECTION

Date of Assignment: 04/02/2021

Date Inspected: 04/02/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
3	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
4	1		*BLOWER ASSY	Not Necessary	656.00 FL	*- FL
5	1		*RADIATOR ASSY	Bent	646.00 FL	*646.00 FL
6	1		*CONDENSER ASSY-COOLER	Bent	687.00 FL	*687.00 FL
7	1		*GUARD-AIR, RH	Broken	28.00 FL	*28.00 FL
8	1		*GUARD-AIR, LH	Not Necessary	28.00 FL	*- FL
9	1		*COOLANT (4L)	Not Necessary	26.00 FN	*- FN
10	1		*LAMP ASSY-HEAD, RH	Broken	1,219.00 FL	*1,219.00 FL
11	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
12	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
13	1		*STIFFNER-FR UPR LWR	Not Necessary	114.00 FL	*- FL
14	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
15	1		*LAMP ASSY-SIDE REPEATER, RH	Cut	143.00 FL	*143.00 FL
16	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	14.00 FL	*- FL
17	1		*MOULDING-FRONT BUMPER, RH	Cut	36.00 FL	*36.00 FL
18	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FL	*38.00 FL
19	10		*CLIP	Necessary	10.00 FL	*10.00 FL
20	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
21	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
22	1		*CAP-FRONT HOOK	Crushed	9.00 FL	*9.00 FL
23	1		*GRILLE-FRONT BUMPER	Cut	262.00 FL	*262.00 FL
24	1		*COVER-FR BUMPER FOG LAMP, RH	Not Necessary	15.00 FL	*- FL
25	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
26	1		*HINGE ASSY-HOOD, RH	Bent	43.00 FL	*43.00 FL
27	1		*HINGE ASSY-HOOD, LH	Bent	43.00 FL	*43.00 FL
28	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
29	1		*INSULATOR-FENDER RH	Not Necessary	27.00 FL	*- FL
30	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
31	1		*ROD ASSY-HOOD STAY	Torn	35.00 FL	*35.00 FL
32	1		*LATCH ASSY-HOOD	Not Necessary	103.00 FL	*- FL
33	1		*WIRING ASSY-FEM (Supplementary)	Broken	143.00 FL	*143.00 FL
34	1		*HORN ASSY-LOW PITCH (Supplementary)	Broken	74.00 FL	*74.00 FL
35	1		*COVER ASSY-COWL TOP (Supplementary)	Cut	247.00 FL	*247.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	8,921.00	7,367.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,769.00	1,469.40
- Nett Item Discount on N Items 23.00/23.00% (S\$)	5.98	0.00
Total Parts (S\$)	7,146.02	5,897.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT FENDER	New	2,400.00	1,600.00
2	REMOVE AND REPLACE RADIATOR AND A/C CONDENSER	New	100.00	100.00
3	TOP UP A/CON GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
4	PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER FACE, RH FRONT DOOR, RH FRONT FENDER, LH FRONT FENDER AND AFFECTED PORTION	New	2,100.00	1,750.00
5	APPLY BODY SEALANT	New	120.00	40.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	PERFORM RUST PREVENTION	New	120.00	40.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	50.00
10	RE-APPLY ZERONA COATING	New	400.00	0.00
Gross Labour Cost (\$\$)			5,520.00	3,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >