



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. VCT 3242

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET MIRROR (CONSISTENT)	NOT NECESSARY	125.00	-
1	HANDLE BAR (CONSISTENT)	DISTORTED	95.00	95.00
1	SET STEERING CONE & BEARING (CONSISTENT)	DAMAGED	125.00	125.00
1	BRAKE LEVER (CONSISTENT)	CUT	75.00	75.00
1	SET BALANCER (CONSISTENT)	NOT NECESSARY	120.00	-
1	HEAD LAMP (CONSISTENT)	SCRATCHED	320.00	320.00
1	FRONT HEAD COWLING (CONSISTENT)	CUT	250.00	250.00
1	FRONT INNER PANEL (CONSISTENT)	CUT	120.00	120.00
1	HORN COVER (CONSISTENT)	NOT NECESSARY	90.00	-
1	FRONT INNER BRACKET PANEL (CONSISTENT)	NOT NECESSARY	95.00	-
1	FRONT MUDGUARD (CONSISTENT)	BROKEN	185.00	185.00
1	SET FORK TUBE (CONSISTENT)	BENT	480.00	480.00
1	FORK UNDER BRACKET (CONSISTENT)	DAMAGED	250.00	250.00
1	FRONT RIM (CONSISTENT)	DISTORTED	320.00	320.00
1	BRAKE DISC (CONSISTENT)	NOT NECESSARY	190.00	-
1	WHEEL AXLE (CONSISTENT)	BENT	125.00	125.00
1	FRONT SIDE PANEL L/RH (CONSISTENT)	CRACKED / CUT	280.00	280.00
1	FOOTREST (N/S REAR) (CONSISTENT)	BROKEN	65.00	65.00
1	GEAR PEDAL (CONSISTENT)	NOT NECESSARY	75.00	-
1	REAR SIDE PANEL LH (CONSISTENT)	NOT NECESSARY	165.00	-
1	PILLION GRIP BAR (CONSISTENT)	CUT	85.00	85.00
1	REAR LH SIGNAL (CONSISTENT)	CRACKED	65.00	65.00
1	TAILLAMP (CONSISTENT)	MTG BROKEN	150.00	150.00
1	VISOR (CONSISTENT)	CUT	180.00	180.00
	LESS 10% DISCOUNT		-403.00	-317.00
			3,627.00	2,853.00
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	15.00	15.00
			15.00	15.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NECESSARY PARTS ,ALIGN & ETC.		250.00	150.00
	REMOVE & REPLACE FORK TUBE ,OIL SEAL,FORK UNDER BRACKET ,FORK RIM ,BRAKE DISC & REALIGN BACK THE SAME.		200.00	80.00
	SUPPLY BODY DECAL STICKER .		120.00	80.00
	REALIGN BODY FRAME.	NOT NECESSARY	280.00	-
			890.00	310.00
GRAND TOTAL			4,532.00	3,178.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CC4/ASM21001692/Dga3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.