



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE ANG			Ref: CC4/ASM21001692/Dga3q2 Date: 01/03/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHA 1007A	Veh. Inspected	VCT 3242
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03584	Excess (\$)	0.00
	Assign From		Assign Date	04/02/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA 135 LC	c.c	134
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	PMYUG0810K0084748	Colour	GREEN
	Odometer	-	Steering	FAULTY
	Brakes	FAULTY	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	70/90 R17	PIRELLI	2 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90 R17	PIRELLI	2 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	31/01/2021	Inspection Date	05/02/2021
	Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	