

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001693/GGS3Q2
Date: 06/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100462958-05
Claimant Vehicle No :	SMV3034M	Insured Vehicle No :	SLC461U
Date of Loss:	02/02/2021	Nature of Claim:	TP
		Claim No:	5795220357SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV3034M		
Make & Model:	AUDI R8, 4.2 FSI QU R-TRONIC (A)	Engine No:	BYH005567
Reg. Date:	06/03/2008 (Man. Year: 2007)	Chassis No:	WUAZZZ4268N004178
Colour:	Green	Odometer:	75113 km
Engine Capacity:	4163 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	295/30Z R19	Rear Tyre Size:	295/30Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,472.24	15,992.23	6,480.01	28.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	960.00	1,600.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,032.24	16,952.23	8,080.01	32.28
Approved Total (Overridden) (S\$)		13,550.00		

(S\$)	25,032.24	13,550.00	11,482.24	45.87
+ GST 7.00/7.00% (S\$)	1,752.26	948.50	803.76	45.87
Nett Amount (S\$)	26,784.50	14,498.50	12,286.00	45.87
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		15,065.95		

INSPECTION

Date of Assignment: 04/02/2021

Date Inspected: 11/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	3,304.80 FL	*3,304.80 FL
2	1		*FRONT BUMPER LOWER LIP	Not Necessary	720.00 FL	*- FL
3	1		*FRONT BUMPER RETAINER	Not Necessary	71.40 FL	*- FL
4	1		*FRONT BUMPER SPONGE	Cracked	310.00 FL	*220.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,065.90 FL	*- FL
6	2		*FRONT BUMPER SIDE COVER	Broken (1 PCS ONLY)	682.80 FL	*238.18 FL
7	1		*FRONT GRILLE	Cracked	2,226.00 FL	*2,226.00 FL
8	1		*FRONT GRILLE EMBLEM	Necessary	154.00 FL	*85.00 FL
9	1		*RADIATOR	Not Necessary	1,754.50 FL	*- FL
10	1		*RADIATOR HOUSING (NPA)	Not Necessary	0.00 FL	*- FL
11	2		*FRONT PDC SENSOR	Not Necessary	423.20 FL	*- FL
12	1		*BONNET	Bent	10,844.50 FL	*10,844.50 FL
13	1		*BONNET EMBLEM	Necessary	280.00 FL	*99.00 FL
14	1		*BONNET EMBLEM -QUATTRO	Necessary	260.00 FL	*85.00 FL
15	1		*SET FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
16	1		*SET FRONT GRILLE CLIP	Necessary	50.00 FS	*30.00 FS
17	1		*BOT COOLANT	Not Necessary	120.00 FS	*- FS
18	1		*NUMBER PLATE	Cracked	80.00 FS	*40.00 FS
19	1		*STICKER	Necessary	1,200.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,577.10	17,702.48
- List Item Discount on L Items 5.00/10.00% (\$\$)	1,104.86	1,710.25
Total Parts (\$\$)	22,472.24	15,992.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	0.00
2	REMOVE AND TRIMS AND GARNISHES TO FACILITATE REPAIR	New	150.00	60.00
3	REMOVE AND REFIT RADIATOR AND TOP UP COOLANT	New	200.00	0.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	500.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	400.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			2,560.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >