

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ZSU600095021

HOCK CHUAN HONG CORPORATION PTE LTD
14 TUAS SOUTH STREET 12
S 636953

TP Lon Pac.
Jasper

Vehicle No :SLP 4961 Z
Make/Model :TOYOTA HARRIER
Accident date :02.02.2021

No	DESCRIPTION	Qty	Amount (S\$)
List Items			
1	Front bumper towing hook cover <i>Missing</i>	1	\$ 73.40 ✓
2	Front bumper <i>Distorted</i>	1	\$ 1595.00 ✓ 1450
3	Front bumper side holder @ \$112.40 <i>LH Danyd</i>	2	\$ 224.80 ✓ 112.40
4	Front bumper LH fod lamp <i>cracked</i>	1	\$ 273.10 ✓
5	Front bumper LH fod lamp garnish <i>cracked</i>	1	\$ 94.80 ✓
6	Front bumper centre lower grille <i>cut</i>	1	\$ 446.20 ✓
7	Front bumper reinforcement <i>Best</i>	1	\$ 373.70 ✓
8	Front bumper bracket @ \$149.30 <i>Not new</i>	2	\$ 298.60 +
9	Front bumper sponge @ \$194.40 <i>LH cracked</i>	2	\$ 194.40 ✓
10	Front grille <i>cracked</i>	1	\$ 589.10 ✓
11	Front LH fender <i>Distorted</i>	1	\$ 1113.20 ✓ 764
12	Front LH fender inner shield <i>Defaced</i>	1	\$ 449.90 ✓ 218
13	Front LH fender quarter garnish <i>Not new</i>	1	\$ 145.30 +
14	Front LH headlamp <i>cracked</i>	1	\$ 3506.10 ✓ 302
15	Front LH headlamp lower garnish <i>new</i>	1	\$ 218.70 +
16	Front engine lower garnish <i>Not new</i>	1	\$ 686.10 +
17	Front engine lower cover <i>Not new</i>	1	\$ 445.50 ✓ 301
18	Front LH knuckle arm	1	\$ 668.40 +
19	Front LH knuckle arm bearing <i>Not new</i>	1	\$ 514.00 +
20	Front LH lower arm	1	\$ 612.80 +
21	Front LH door side mirror <i>Danyd</i>	1	\$ 1460.90 ✓ 1303
22	Front support panel <i>new</i>	1	\$ 871.50 +
			\$ 14855.50
	Less 25% Disc		\$ 3713.88
	Total		\$ 11141.63

9688 20
727440
887757

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

HOCK CHUAN HONG CORPORATION PTE LTD
14 TUAS SOUTH STREET 12
S 636953

Vehicle No :SLP 4961 Z
Make/Model :TOYOTA HARRIER
Accident date :02.02.2021

No	DESCRIPTION	Qty	Amount (S\$)
----	-------------	-----	--------------

Special Nett Items

1	Front bumper clips (1 set) <i>nu</i>	1	\$ 60.00 30
2	Front LH fender inner shield clips (1 set) <i>nu</i>	1	\$ 60.00 30
3	Front LH tyre <i>stem</i>	1	\$ 380.00 <i>x</i>
4	Front LH sport rim <i>ut</i>	1	\$ 880.00 700
		Total	\$ 1380.00

Labour Cost

1	To check wheel alignment	\$	100.00 80
2	Remove & reinstall front LH suspension	\$	300.00 <i>x</i>
3	Remove ,replace & repair consistent to the accident	\$	1400.00 <i>600</i>
4	Respray painting	\$	1300.00 <i>600</i>
5	Tuff kote	\$	100.00 50
		Total	\$ 3200.00

Grand Total \$ **15721.63**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 9364.407

w/s 7.5k

06 Days

8k