

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001701/KRS3Q2
Date: 19/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	100882226
Claimant Vehicle No :	GBJ1507Y	Insured Vehicle No :	GBK8166X
Date of Loss:	03/02/2021	Nature of Claim:	TP
		Claim No:	0055409605SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ1507Y		
Make & Model:	TOYOTA HIACE, 2.5 (A)	Engine No:	1KD2834406
Reg. Date:	16/01/2019 (Man. Year: 2018)	Chassis No:	JTFHT02P400246853
Colour:	Silver	Odometer:	129276 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,489.39	9,867.96	2,621.43	20.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	3,020.00	860.00	22.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,369.39	12,887.96	3,481.43	21.27
Approved Total (Overridden) (S\$)		10,500.00		

Nett Amount (S\$)	16,369.39	10,500.00	5,869.39	35.86
+ Car Rental (18.0 x S\$100.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		12,307.49		

INSPECTION

Date of Assignment: 04/02/2021

Date Inspected: 05/02/2021

Estimated Period of Repair: 12.0 days

Inspected At:

Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming Autocare
 Singapore 575721

Adjuster: ACCUSER4**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	517.20 FL	*374.45 FL
2	2		*REAR BUMPER SIDE CLIPS	Necessary	60.00 FL	*60.00 FL
3	4		*REAR BUMPER INNER BRACKET	Distorted	154.00 FL	*154.00 FL
4	1		*REAR BUMPER INNER REINFORCEMENT	No such part	382.00 FL	*- FL
5	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
6	1		*TAILLAMP	N/S Cracked	1,154.40 FL	*366.20 FL
7	1		*TAILLAMP LOWER GARNISH	N/S Bent	189.60 FL	*94.80 FL
8	1		*TAILLAMP PANEL	N/S Bent	682.00 FL	*341.00 FL
9	1		*REAR TAILGATE	Bent	2,162.72 FL	*1,956.20 FL
10	1		*REAR TAILGATE OUTER BLACK HANDLE	Warped	201.40 FL	*201.40 FL
11	1		*REAR TAILGATE CENTRE TOYOTA LOGO	Necessary	66.20 FL	*66.20 FL
12	1		*REAR TAILGATE LH TOYOTA EMBLEM	Necessary	24.00 FL	*24.00 FL
13	1		*REAR TAILGATE LH HIACE EMBLEM	Necessary	39.00 FL	*39.00 FL
14	1		*REAR TAILGATE TOP LOCK	Jammed	289.70 FL	*289.70 FL
15	1		*REAR TAILGATE CENTRAL LOCK	Dented	260.10 FL	*260.10 FL
16	1		*REAR TAILGATE LOWER LOCK CATCH	Distorted	85.00 FL	*85.00 FL
17	1		*REAR TAILGATE WEATHERSTRIP	Cut	391.20 FL	*381.90 FL
18	1		*REAR TAILGATE INNER TRIM BOARD	Warped	186.70 FL	*165.00 FL
19	1		*SET REAR TAILGATE INNER BOARD CLIPS	Necessary	50.00 FL	*50.00 FL
20	1		*REAR TAILGATE WINDSCREEN GLASS	Shattered	1,340.00 FL	*1,015.00 FL
21	1		*REAR END PANEL INNER	Bent	1,104.70 FL	*1,104.70 FL
22	1		*REAR END PANEL OUTER	Bent	580.10 FL	*580.10 FL
23	1		*REAR FLOOR PANEL	Bent / Buckled	1,888.50 FL	*1,850.00 FL
24	1		*REAR FLOOR PANEL TOP BEAM	Dented	270.70 FL	*174.10 FL
25	1		*REAR LOWER SPARE TYRE CARRIER	Distorted	247.80 FL	*247.80 FL
26	1		*REAR LOWER EXHAUST SILENCER	Repair	538.20 FL	*- FL
27	2		*REAR EXHAUST SILENCER MOUNTING	Serviceable	76.00 FL	*- FL
28	1		*SET REVERSE SENSORS	Cracked	250.00 FS	*200.00 FS
29	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
30	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*SET REAR END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
32	1		*REAR TAILGATE RH 5PAX STICKER	Necessary	15.00 FS	*12.00 FS
33	1		*REAR TAILGATE LH 70KM/H STICKER	Necessary	15.00 FS	*12.00 FS
34	1		*SIDE REAR LH BODY PANEL	Buckled	1,546.90 FL	*1,546.90 FL
35	1		*SIDE REAR LH BODY INNER PANEL	Bent	722.60 FL	*722.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FLOOR PANEL TOP COVER	Dented	205.80 FL	*205.80 FL
37	1		*REAR LH BODY PANEL AIR DUCT	Cracked	36.00 FL	*36.00 FL
38	1		*REAR FLOOR PANEL WOODEN BOARD	Cracked	380.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,362.52	12,975.95
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,873.13	3,107.99
Total Parts (\$\$)	12,489.39	9,867.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AND REPLACEMENT OF DAMAGES	New	1,400.00	1,200.00
2	TO PUTTY AND SPRAY SPRAY PAINTINGS CHARGES	New	1,800.00	1,400.00
3	TO REMOVE ,REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
4	TO CHECK WIRING AND LIGHTINGS	New	60.00	20.00
5	TO REMOVE ,REFIT REVERSE SENSORS	New	80.00	50.00
6	TO REMOVE ,REFIT REAR TAILGATE FITTINGS	New	80.00	60.00
7	TO REMOVE, REFIT REAR UPHOLSTERY AND ATTACHMENTS	New	150.00	80.00
8	TO REMOVE,REFIT REAR EXHAUST SILENCER	New	80.00	0.00
9	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	90.00	90.00
Gross Labour Cost (\$\$)			3,880.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >