

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBJ1507Y

No.	Qty	List Items				
					374.45	
1	1	Rear bumper	\$	B ₁	517.20 ✓	
2	2	Rear bumper side clips	\$	M	60.00 ✓	
3	4	Rear bumper inner bracket	\$	Dir	154.00 ✓	
4	1	Rear bumper inner reinforcement	\$	NJP	382.00 X	
5	1 set	Rear bumper clips	\$	M	40.00 ✓	
6	2	Taillamp	NISCM	\$	1,154.40 ✓	
7	2	Taillamp lower garnish	NIS B ₁	\$	189.60 ✓	
8	2	Taillamp panel	NIS B ₁	\$	682.00 ✓	
9	1	Rear tailgate	\$	B ₁	2,162.72 ✓	
10	1	Rear tailgate outer black handle	\$	Wap	201.40 ✓	
11	1	Rear tailgate centre "TOYOTA" logo	\$	M	66.20 ✓	
12	1	Rear tailgate LH "TOYOTA" emblem	\$	M	24.00 ✓	
13	1	Rear tailgate LH "HIACE" emblem	\$	M	39.00 ✓	
14	1	Rear tailgate top lock	\$	T ₁	289.70 ✓	
15	1	Rear tailgate central lock	\$	Del	260.10 ✓	
16	1	Rear tailgate lower lock catch	\$	Dir	85.00 ✓	
17	1	Rear tailgate weatherstrip	\$	WT	391.20 ✓	
18	1	Rear tailgate inner trim board	\$	Wap	186.70 ✓	
19	1 set	Rear tailgate inner board clips	\$	M	50.00 ✓	
20	1	Rear tailgate windscreen glass	1015 Shatter	\$	1,340.00 ✓	
21	1	Rear end panel inner	F57068-26320	\$	B ₁	1,104.70 ✓
22	1	Rear end panel outer		\$	B ₁	580.10 ✓
23	1	Rear floor panel	1850 BT/B ₁	\$	1,888.50 ✓	
24	1	Rear floor panel top beam	174.10	\$	Del	270.70 ✓
25	1	Rear lower spare tyre carrier		\$	Dir	247.80 ✓
26	1	Rear lower exhaust silencer		\$	R	538.20 X
27	2	Rear exhaust silencer mounting		\$	M	76.00 X
			\$		12,981.22	
			Less 25%	\$	3,245.31	
			Total :	\$	9,735.92	

Special Nett Items

28	1 set	Reverse sensors	\$	CM	250.00 2005n
29	1	Rear number plate	\$	Sn	50.00 X
30	1 set	Rear windscreen sealant	\$	M	80.00 405n
31	1 set	Rear end panel sealant	\$	M	80.00 305n
32	1	Rear tailgate RH "5pax" sticker	\$	M	15.00 125n
33	1	Rear tailgate LH "70km/h" sticker	\$	M	15.00 125n
			Total :	\$	490.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,400.00 1200l
2	To putty and spray Spray Paintings charges.	\$	1,800.00 1400l
3	To remove, refit rear windscreen glass.	\$	140.00 120l

Not Authorized
 11 Sep @ 10.50am
 Running After Paint
 12 days

4	To check wirings and lightings.	\$	60.00	20%
5	To remove, refit reverses sensors.	\$	80.00	50%
6	To remove, refit rear tailgate fittings.	\$	80.00	60%
7	To remove, refit rear upholstery and attachments.	\$	150.00	80%
8	To remove, refit rear exhaust silencer.	\$	80.00	x
9	To supply and apply anti rust treatment	\$	90.00	✓
Total :		\$	3,880.00	

Total Parts and Labour : \$ 14,105.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

8-02-2021

SUPPLEMENTARY REPAIR ESTIMATE FOR Toyota Hiace - GBJ 1507 Y

- 1 pc. Side Rear LH body panel
- 1 pc. Side Rear LH body inner panel
- 1 pc. Rear floor panel top cover
- 1 pc. Rear LH body panel air duct

Bu \$ 1,546.90 ✓
R 722.60 ✓
nd 205.80 ✓
cm 36.00 ✓

2,511.30

Less 25%

627.83
\$ 1,883.47

\$ 1,883.47

- Special Nett
- 1 pc. Rear floor panel wooden board

cm 380.00 *250m*

TOTAL

\$ 2,263.47