

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 813Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (SN)	TORN	1,421.95	1,421.95
1	FRONT BUMPER COMPANY SIGN (SN)	NECESSARY	63.68	63.68
2	FRONT DISTANCE SENSOR (SN)	SERVICEABLE	364.96	-
2	SPACER RING (SN)	NOT NECESSARY	12.70	-
1	RH/HEADLAMP COVER (SN)	SERVICEABLE	70.74	-
1	RH/HEADLAMP COVER SPRING (SN)	SERVICEABLE	4.93	-
1	RH/FRONT FENDER INTERMEDIATE LAYER (SN)	SERVICEABLE	17.94	-
1	RH/HEADLAMP (SN)	SERVICEABLE	2,632.90	-
1	RH/HEADLAMP SEALING FRAME (SN)	SERVICEABLE	75.02	-
1	RH/HEADLAMP CONTROL UNIT (SN)	SERVICEABLE	870.27	-
1	RH/HEADLAMP RANGE ADJUSTMENT (SN)	SERVICEABLE	314.71	-
1	FRONT CROSS MEMBER (SN)	SERVICEABLE	340.68	-
1	RH/FRONT CROSS MEMBER ABSORBER (SN)	SERVICEABLE	160.37	-
1	NO PLATE (SN) (ADDITIONAL)	BENT	60.00	60.00
1	CTR/BASIC MOUNTING FOR BUMPER (SN) (ADDITIONAL)	CRACKED	179.22	179.22
			6,590.07	1,724.85
	<u>LABOUR</u>			
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		1,920.00	960.00
	RESPRAY FRONT BUMPER.		960.00	600.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	TO REMOVE, REPLACE HEADLAMP WITH FOCUS.		120.00	120.00
			3,380.00	2,060.00
	GRAND TOTAL		9,970.07	3,784.85



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		3,784.85
LESS EXCESS		-500.00
NETT LIABILITY		3,284.85

Report Ref No. CS/UOI21001704/R1td3e2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser**