

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001708/BPA3Q2
Date: 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900096745
Claimant Vehicle No :	SJY3385U	Insured Vehicle No :	SMF7703Z
Date of Loss:	03/02/2021	Nature of Claim:	TP
		Claim No:	9392991239SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY3385U	Engine No:	G4FCAU871160
Make & Model:	HYUNDAI 130, 1.6 FD (A)	Chassis No:	KMHDC81DMAU080793
Reg. Date:	24/08/2010 (Man. Year: 2010)	Odometer:	14306 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,603.76	7,387.60	5,216.16	41.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	2,560.00	2,320.00	47.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,483.76	9,947.60	7,536.16	43.10
Approved Total (Overridden) (S\$)		7,950.00		
(S\$)	17,483.76	7,950.00	9,533.76	54.53
+ GST 7.00/7.00% (S\$)	1,223.86	556.50	667.36	54.53
Nett Amount (S\$)	18,707.62	8,506.50	10,201.12	54.53
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
(S\$)		9,148.50		
Liab Amount (85.00%) (S\$)		7,776.23		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,783.68		
Global Sum Settlement (S\$)		7,780.00		

INSPECTION

Date of Assignment:	04/02/2021	Inspected At:	160 Sin Ming Dr #01-14
Date Inspected:	05/02/2021	Repairer :	Team Autopro Pte Ltd - Sin Ming (HQ)
Estimated Period of Repair:	8.0 days		

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,062.20 FL	*1,062.20 FL
2	1		*BONNET LOCK	Jammed	65.00 FL	*65.00 FL
3	2		*BONNET HINGE	Bent	137.80 FL	*120.00 FL
4	1		*BONNET INSULATOR	Not Damaged	128.60 FL	*- FL
5	1		*FRONT BUMPER	Broken	631.50 FL	*566.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	101.20 FL	*54.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Dented	285.60 FL	*255.00 FL
8	1		*FRONT BUMPER INNER SPONGE	Broken	140.00 FL	*97.00 FL
9	1		*FRONT BUMPER CENTRE GRILLE	Broken	157.60 FL	*157.60 FL
10	1		*FRONT BUMPER FOG LAMP RH	Cut	155.00 FL	*155.00 FL
11	2		*FRONT BUMPER BRACKET	Dented	156.00 FL	*62.00 FL
12	1		*FRONT GRILLE	Broken	356.20 FL	*356.20 FL
13	1		*FRONT GRILLE LOGO	Necessary	58.00 FL	*45.00 FL
14	1		*FRONT SUPPORT PANEL	Broken	986.50 FL	*753.00 FL
15	1		*FRONT FENDER	N/S Repair / O/S Dented	1,192.00 FL	*389.00 FL
16	1		*FRONT FENDER INNER COWLING	O/S Torn	373.00 FL	*158.00 FL
17	2		*FRONT FENDER INSULATOR	No such part	169.20 FL	*- FL
18	1		*FRONT DOOR RH	Repair	1,173.00 FL	*- FL
19	1		*FRONT DOOR BLACK TAPE RH	Not Damaged	38.40 FL	*- FL
20	1		*FRONT DOOR WEATHERSTRIP RH	Not Damaged	122.30 FL	*- FL
21	2		*HEADLAMP	Broken	1,213.00 FL	*1,213.00 FL
22	2		*HEADLAMP LOWER BRACKET	No such part	172.20 FL	*- FL
23	1		*FRONT SHOCK ABSORBER RH	Dented	297.80 FL	*211.00 FL
24	1		*FRONT LOWER ARM RH	Bent	394.50 FL	*282.00 FL
25	1		*FRONT KNUCKLE ARM RH	Dented	423.00 FL	*352.00 FL
26	1		*FRONT KNUCKLE ARM BEARING RH	Jammed	211.60 FL	*211.60 FL
27	1		*WASHER TANK	Broken	188.60 FL	*114.60 FL
28	1		*WASHER TANK MOTOR	Not Damaged	135.60 FL	*- FL
29	1		*RADIATOR	Bent	597.80 FL	*597.80 FL
30	1		*RADIATOR SPARE TANK	Broken	98.00 FL	*98.00 FL
31	1		*AIR CON CONDENSOR	Bent	947.00 FL	*947.00 FL
32	1		*AIR CON HIGH PRESSURE PIPE	Not Damaged	388.60 FL	*- FL
33	1		*AIR CON LOW PRESSURE PIPE	Not Damaged	347.90 FL	*- FL
34	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
35	1		*BONNET SEALANT	Necessary	100.00 FS	*40.00 FS
36	1		*BONNET INSULATOR CLIPS	Necessary	50.00 FS	*30.00 FS
37	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*FRONT BUMPER CENTRE GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*FRONT FENDER SEALANT	O/S Necessary	200.00 FS	*60.00 FS
41	1		*FRONT FENDER INNER COWLING CLIPS	O/S Necessary	100.00 FS	*30.00 FS
42	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
43	1		*FRONT ALLOY RIM RH	Dented	780.00 FS	*350.00 FS
44	1		*FRONT TYRE RH	Not Damaged	480.00 FS	*- FS
45	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
46	1		*AIR CON FLUID	Necessary	80.00 FS	*40.00 FS
47	1		*FRONT NUMBER PLATE W/CASING	Dented	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,184.70	9,052.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,580.94	1,664.40
Total Parts (\$)	12,603.76	7,387.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BONNET COMPONENT	New	150.00	80.00
2	R&R FRONT UNDER CARRIAGE PARTS	New	350.00	150.00
3	R&R FRONT TYRE AND BALANCING	New	100.00	60.00
4	WHEEL ALIGNMENT	New	180.00	60.00
5	R&R RADIATOR	New	150.00	60.00
6	R&R AIR CON CONDENSOR	New	150.00	60.00
7	CHECK WIRING	New	100.00	30.00
8	UPHOLSTERY	New	300.00	0.00
9	PANEL BEATING	New	1,600.00	1,000.00
10	RUST PROOFING	New	200.00	60.00
11	SPRAY PAINTING	New	1,600.00	1,000.00
			Gross Labour Cost (\$)	4,880.00
				2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >