

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS4/FWD21001723/NQF3E2
Date: 08/03/2021

REFERENCE

Insured/Claimant: TUAN SUFIYAN BIN TUAN BAHARUDIN Policy No: PNPV2020-00010255
Date of Loss: 03/02/2021 Nature of Claim: OD Claim No: 1202100000710

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ8886L**
Make & Model: BMW 116I, 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A) Engine No: A609J673N13B16A
Reg. Date: 20/03/2014 (Man. Year: 2014) Chassis No: WBA1A12020P575970
Colour: Blue Odometer: 0 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: 0 mm Rear Left Side: 0 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/02/2021 Present Location: Ah Lim Motor Company (Sin Ming)
Date Inspected: 05/02/2021 Inspected At: Ah Lim Motor Company (Sin Ming)
Estimated Period of Repair: 0.0 days 176 Sin Ming Drive #05-12, Sin Ming AutoCare
Singapore 575721

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$53,000.00
OMV :	\$26,819.00
PARF Rebate (1) :	\$12,705.00
Quota Premium Paid :	\$72,290.00
COE Rebate (2) :	\$22,464.00
Total Rebate (1) + (2) = :	\$35,169.00

The total amount incurred will be Market Value \$53,000.00 minus Total Rebate \$35,169.00 = \$17,831.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2021)
Parts:	144	BMW 116I 1.6 ABS D/AIRBAG 2WD 5DR HID DSC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ8886L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Vehicle Sustains Extensive Damages - Beyond Repairs	New	0.00	0.00
Gross Labour Cost (\$\$)			0.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >