

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21001734/T1TD3E2

Date: 17/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100498168
Claimant Vehicle No : FBK5693K **Insured Vehicle No :** SLK4809H
Date of Loss: 02/02/2021 Nature of Claim: TP Claim No: 7269004052SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK5693K**
Make & Model: KYMCO KA40AA, 163cc Engine No: KA401106550
Reg. Date: 27/10/2015 (Man. Year: 2015) Chassis No: LC2D21000F3100367
Colour: White/Green Odometer: 259710 km
Engine Capacity: 163 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R12 Rear Tyre Size: 130/70 R12
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/02/2021
Date Inspected: 05/02/2021 Inspected At: 3 Motorwerkz Concepts Pte Ltd (HQ)
25 Kaki Bukit Road 4, Synergy @ KB #01-40
Singapore 417800
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
3	1		*FRONT FORK ASSY	* Check	0.00 F	*- F
4	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
5	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
6	1		*FRONT LH SIGNAL LAMP	Cut	0.00 F	*- F
7	1		*ERP BRACKET	Bent	-	-
8	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
9	1		*CLUTCH LEVER	Cut	0.00 F	*- F
10	1		*SIDE FAIRING LH	Cut	0.00 F	*- F
11	1		*SIDE FAIRING INNER GARNISH LH	Cut	0.00 F	*- F
12	1		*REAR FAIRING LH	Cut	0.00 F	*- F
13	1		*STEP GARNISH LH	Cut	0.00 F	*- F
14	1		*LOWER STEP GARNISH LH	Cut	0.00 F	*- F
15	1		*SIDE STAND	Bent	0.00 F	*- F
16	1		*MAIN STAND	Bent	0.00 F	*- F
17	1		*REAR BOX	Cut	0.00 F	*- F
18	1		*REAR SIDE COVER LH	Cut	0.00 F	*- F
19	1		*ERP UNIT	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >