

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001742/KVF3E2

Date: 06/04/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00121022000
Claimant Vehicle No: SFJ9988S Insured Vehicle No: GBC8179B
Date of Loss: 02/02/2021 Nature of Claim: TP Claim No: SNM21D200682/C03/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFJ9988S**
Make & Model: TOYOTA SIENTA, 1.5 CVT ELEGANCE (A) Engine No: 2NRX342980
Reg. Date: 26/06/2018 (Man. Year: 2018) Chassis No: MHFZ28H3300055285
Colour: Metallic Grey Odometer: 44685 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16
Front Left Side: Bridgestone 3 mm Rear Left Side: Bridgestone 2 mm
Front Right Side: Bridgestone 3 mm Rear Right Side: Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,372.00	5,647.00	725.00	11.38
Miscellaneous Items	395.00	245.00	150.00	37.97
Labour	1,339.80	953.40	386.40	28.84
Paintwork Labour	577.80	595.85	-18.05	-3.12
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,684.60	7,441.25	1,243.35	14.32
+ GST 7.00/7.00% (S\$)	607.92	520.89	87.03	14.32
Nett Amount (S\$)	9,292.52	7,962.14	1,330.38	14.32

INSPECTION

Date of Assignment: 05/02/2021 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 05/02/2021 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Apr 2021)

Parts: M1-MPV TOYOTA SIENNA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFJ9988S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*Spare Parts		5,652.00 F	*4,927.00 F	
Supplementary #1							
2	1		*WASHER CONTAINER	Dented	65.00 F	*65.00 F	
3	1		*COND TUBE	Bent	165.00 F	*165.00 F	
4	1		*RADIATOR SHROUD	Dented	100.00 F	*100.00 F	
5	1		*R/F AIR DUCT	Cracked	40.00 F	*40.00 F	
6	1		*RAD S/SEAL LOWER	Dented	40.00 F	*40.00 F	
7	1		*RAD S/SEAL LOWER LH	Dented	40.00 F	*40.00 F	
8	1		*BONNET STOPPER	Missing	10.00 F	*10.00 F	
9	1		*AIR FUEL SENSOR	Bent	180.00 F	*180.00 F	
10	1		*R/F S-MEMBER REINF	Bent	80.00 F	*80.00 F	
					Total Parts (S\$)	6,372.00	5,647.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	395.00	245.00
			Sub Total (\$\$)	245.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	577.80	595.85
<u>Labour Items</u>				
2	Total of Labour	New	1,339.80	953.40
			Gross Labour Cost (\$\$)	1,549.25

Report was unsubmitted during this print-out.

< END OF ESTIMATES >