

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21001743/AGTF3Q2
Date: 19/03/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001362526
Claimant Vehicle No :	SMK8272S	Insured Vehicle No :	GBE7089Z
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	253028

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK8272S	Engine No:	L15B4313018
Make & Model:	HONDA FREED, 1.5 G (A)	Chassis No:	GB51091058
Reg. Date:	25/04/2019 (Man. Year: 2018)	Odometer:	50530 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Winrun 6 mm	Rear Left Side:	Winrun 6 mm
Front Right Side:	Winrun 6 mm	Rear Right Side:	Winrun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,036.32	5,143.68	3,892.64	43.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	2,740.00	1,390.00	33.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,166.32	7,883.68	5,282.64	40.12
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	13,166.32	6,300.00	6,866.32	52.15

INSPECTION

Date of Assignment:	05/02/2021		
Date Inspected:	05/02/2021	Inspected At:	Advance Auto Garage 10 Kaki Bukit Road 2, #01-21 First East Centre Singapore 417868
Estimated Period of Repair:	7.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2021)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK8272S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	753.30 FL	*753.30 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	64.80 FL	*64.80 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	180.00 FL	*- FL
4	1		*REAR END PANEL	Dented	509.40 FL	*509.40 FL
5	1		*REAR END PANEL TOP GARNISH	Deformed	208.00 FL	*208.00 FL
6	1		*REAR END PANEL INNER	Dented	326.20 FL	*326.20 FL
7	1		*TAILLAMP	O/s Cracked	1,322.00 FL	*661.00 FL
8	1		*TAILGATE	Distorted	1,115.90 FL	*1,115.90 FL
9	1		*TAILGATE LOCK	Damaged	185.90 FL	*185.90 FL
10	1		*TAILGATE WEATHERSTRIPE	Cut	241.70 FL	*241.70 FL
11	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	315.80 FL	*- FL
12	1		*TAILGATE INNER TRIM BOARD	Cracked	288.90 FL	*288.90 FL
13	1		*TAILGATE REFLECTOR	O/s Cracked	736.40 FL	*368.20 FL
14	1		*TAILGATE INNER PULL POCKET	Deformed	55.10 FL	*55.10 FL
15	1		*TAILGATE GLASS MOULDING	Necessary	85.90 FL	*85.90 FL
16	1		*HONDA LOGO	Necessary	38.40 FL	*38.40 FL
17	1		*FREED EMBLEM	Necessary	56.90 FL	*56.90 FL
18	1		*FLOOR PANEL	Repair	1,578.00 FL	*- FL
19	1		*FLOOR PANEL TOP MAT	Not Necessary	588.20 FL	*- FL
20	2		*REAR FENDER INNER TRIM BOARD	Cracked	848.20 FL	*848.20 FL
21	1		*REAR EXHAUST PIPE	Not Necessary	971.10 FL	*- FL
22	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	28.50 FL	*- FL
23	1		*REAR BUMPER INNER GARNISH LH	Torn	46.80 FL	*46.80 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
26	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
28	1		*SET TAILGATE OUTER CHROME MOULDING CLIPS	Not Necessary	20.00 FS	*- FS
29	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*SET TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
31	2		*SETS REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,145.40	6,314.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,109.08	1,170.92
Total Parts (\$\$)	9,036.32	5,143.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVE AND REFIT PARTS	New	1,600.00	1,100.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	1,100.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE VIDEO RECORDER	New	100.00	50.00
8	TO REMOVE UPHOLSTERY	New	150.00	100.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
11	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			4,130.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >