



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21001744/T1Uqd3n2	
			Date: 15/07/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 4426D	Veh. Inspected	GBK 67B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100398/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFAT35Y30K210177	Colour	BLUE
	Odometer	74476 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	GREEN MAX	6 mm
	L/H Front Tyre	195 R15	GREEN MAX	6 mm
	R/H Rear Tyre	155 R12 (D)	GREEN MAX	6/6 mm
	L/H Rear Tyre	155 R12 (D)	GREEN MAX	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/02/2021	Inspection Date	10/02/2021
	Survey held at	HH MOTOR TRADING BLOCK 3012, BEDOK NORTH AVE 4, #01-2054 BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	