

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21001745/AVF3N2**Date:** 07/09/2021**REFERENCE**

Insured/Claimant:	ZHANG NING	Policy No:	1900081017	
Date of Loss:	02/02/2021	Nature of Claim:	OD	Claim No: 1494744551SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK1878R		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)	Engine No:	CHZC27360
Reg. Date:	29/03/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8V3KA056588
Colour:	White	Odometer:	35564 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$97,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,271.00	13,299.84	12,971.16	49.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,892.00	10,917.00	4,975.00	31.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,163.00	24,216.84	17,946.16	42.56
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	41,563.00	23,616.84	17,946.16	43.18
+ GST 7.00/7.00% (S\$)	2,909.41	1,653.18	1,256.23	43.18
Nett Amount (S\$)	44,472.41	25,270.02	19,202.39	43.18

INSPECTION

Date of Assignment:	05/02/2021	
Date Inspected:	05/02/2021	Inspected At: 24 BENOI SECTOR SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	15.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT SIDE MEMBER TRIM-RH	Dented	2,293.00 FS	*1,834.40 FS
2	1	*FRONT FENDER-RH	Dented	851.00 FS	*680.40 FS
3	1	*FRONT FENDER POP RIVET 8 Pcs	Necessary	27.00 FS	*21.12 FS
4	1	*FRONT FENDER ATTACHMENT PARTS-RH	Not Necessary	72.00 FS	*- FS
5	1	*FRONT FENDER BRACE-RH	Not Necessary	96.00 FS	*- FS
6	1	*FRONT FENDER BRACKET-RH	Not Necessary	48.00 FS	*- FS
7	1	*FRONT FENDER CLOSING ELEMENT-RH	Not Necessary	62.00 FS	*- FS
8	1	*FRONT WHEEL HOUSING LINER-RH	Cut	169.00 FS	*134.80 FS
9	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH	Not Necessary	57.00 FS	*- FS
10	1	*FRONT DOOR-RH	Distorted	2,767.00 FS	*2,213.60 FS
11	1	*FRONT DOOR OUTER SEAL-RH	Necessary	161.00 FS	*128.40 FS
12	1	*BONDING AGENT	Not Necessary	49.00 FS	*- FS
13	1	*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
14	1	*APPLICATOR	Not Necessary	8.00 FS	*- FS
15	1	*FRONT DOOR ATTACHMENT PARTS-RH	Not Necessary	241.00 FS	*- FS
16	1	*FRONT DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
17	1	*FRONT DOOR HINGE HALF LOWER PART-RH UPPER	Not Necessary	48.00 FS	*- FS
18	1	*FRONT DOOR HINGE HALF UPPER PART-RH LOWER	Not Necessary	47.00 FS	*- FS
19	1	*FRONT DOOR HINGE HALF LOWER PART-RH UPPER/LOWER	Not Necessary	48.00 FS	*- FS
20	1	*FRONT DOOR HANDLED EXTERIOR-RH	Distorted	374.00 FS	*298.80 FS
21	1	*FRONT DOOR HANDLE CAP-RH	Missing	54.00 FS	*42.48 FS
22	1	*FRONT DOOR SLIDE VALVE-RH	Damaged	22.00 FS	*17.28 FS
23	1	*FRONT DOOR HANDLE SENSOR-RH	Damaged	228.00 FS	*182.40 FS
24	1	*FRONT DOOR UNDERLAY-RH REAR	Damaged	6.00 FS	*4.64 FS
25	1	*FRONT DOOR UNDERLAY-RH FRONT	Damaged	5.00 FS	*3.92 FS
26	1	*FRONT DOOR LOCK CYLINDER-RH	Damaged	504.00 FS	*402.80 FS
27	1	*FRONT DOOR MOUNTING BAR-RH	Damaged	161.00 FS	*128.80 FS
28	1	*FRONT DOOR BOWDEN CABLE	Not Necessary	52.00 FS	*- FS
29	1	*FRONT MIRROR EXTERIOR MOUNTING-RH	Distorted	1,024.00 FS	*819.20 FS
30	1	*FRONT MIRROR CAP-RH	Missing	169.00 FS	*135.20 FS
31	1	*FRONT MIRROR GLASS-RH	Cracked	1,687.00 FS	*1,349.60 FS
32	1	*FRONT WINDOW REGULATOR MOTOR-RH	Not Necessary	268.00 FS	*- FS
33	1	*FRONT CORNER TRIM-RH	Not Necessary	46.00 FS	*- FS
34	1	*FRONT WINDOW GUIDE-RH	Not Necessary	420.00 FS	*- FS
35	1	*FRONT B-PILLAR (BLACK GLOSSY) TRIM-RH	Not Necessary	105.00 FS	*- FS
36	1	*FRONT WINDOW SLOT SEAL-RH	Cut	270.00 FS	*215.60 FS
37	1	*FRONT ROOF MOLDING-RH	Not Necessary	591.00 FS	*- FS
38	1	*FRONT DOOR WINDOW-RH	Cut	231.00 FS	*184.40 FS
39	1	*FRONT ALUMINIUM RIM-RH	Cut	1,166.00 FS	*932.80 FS
40	1	*FRONT ASSEMBLY CARRIER	Bent	1,000.00 FS	*800.00 FS
41	1	*SET OF BONDED RUBBER BUSHES	Torn	112.00 FS	*89.20 FS
42	1	*FRONT LOWER ARM-RH	Bent	373.00 FS	*298.00 FS
43	1	*FRONT WHEEL BEARING-RH	Damaged	579.00 FS	*462.80 FS
44	1	*FRONT WHEEL HUB WITH BEARING-RH	Damaged	478.00 FS	*382.40 FS
45	1	*FRONT GUIDE JOINT-RH	Damaged	124.00 FS	*98.80 FS
46	1	*FRONT COUPLING ROD-RH	Not Necessary	98.00 FS	*- FS
47	1	*FRONT STABILIZER BAR	Not Necessary	395.00 FS	*- FS
48	1	*FRONT GAS SHOCK ABSORBER	Damaged	259.00 FS	*206.80 FS
49	1	*FRONT DRIVE SHAFT-RH	Not Necessary	958.00 FS	*- FS
50	1	*FRONT STEERING GEAR	Not Necessary	4,964.00 FS	*- FS
51	1	*FRONT TRACK ROD-RH	Bent	92.00 FS	*73.04 FS
52	1	*FRONT TIE ROD END-RH	Bent	122.00 FS	*97.20 FS
53	1	*FRONT NOISE INSULATION	Not Necessary	290.00 FS	*- FS
54	1	*UNDERBODY TRIM-RH	Not Necessary	170.00 FS	*- FS
55	1	*REAR B-PILLAR TRIM (BLACK CLOSSY)-RH	Not Necessary	117.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR WINDOW SLOT SEAL-RH	Not Necessary	270.00 FS	*- FS
57	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
58	1		*ACYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
59	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
60	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
61	1		*SUNDRIES	Necessary	400.00 FS	*244.80 FS
62	1		*FRONT DOOR HINGE HALF UPPER PART-RH UPPER	Not Necessary	44.00 FS	*- FS
63	1		*REPAIR SET FOR STEERING BOX (Supplementary)	Necessary	46.00 FS	*36.16 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					26,271.00	13,299.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND REINSTALL FRONT SEAT ASSY,ABCD PILLAR TRIMS,SILL TRIMS,CARPETS,ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	1,800.00
3	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	350.00	280.00
4	TO INSTALL SOLAR FILM FOR RHS FRONT WINDOW GLASS	New	400.00	400.00
5	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
6	TO DISMANTLE AND REINSTALL FRONT BUMPER.TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR.TO CUT OUT AND WELD RHS SILL PANEL.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,900.00	3,250.00
7	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER,RHS FRONT DOOR,RHS REAR DOOR,RHS WING MIRROR COVER,RHS SILL PANEL AND DOOR ENTRANCES	New	5,050.00	2,075.00
8	TO RENEW RHS FRONT RIM WITH TYRE.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			15,892.00	10,917.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >