

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7204S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER COVER	TORN	1,052.20	1,052.20
1	RADIATOR GRILLE	NOT NECESSARY	1,480.00	-
1	BONNET SEAL	TORN	31.90	31.90
10	BUMPER CLIP	NECESSARY	22.00	22.00
1	FRONT BUMPER BRACKET TOP LH	NOT NECESSARY	44.80	-
1	FRONT BUMPER BRACKET SIDE LH	NOT NECESSARY	28.60	-
1	HEAD LAMP LH	NOT NECESSARY	1,800.00	-
1	LH WING MIRROR	BROKEN	670.00	670.00
1	FRONT BUMPER BRACKET SIDE LH	DEFORMED	49.20	49.20
	LESS 20% DISCOUNT		-1,035.74	-365.06
			4,142.96	1,460.24
	SPECIAL NETT ITEMS			
1	FRT COMFORT LOGO STICKER (SN)	NECESSARY	75.00	75.00
1	REAR DOOR COMFORT APP STICKER (SN)	NECESSARY	80.00	80.00
1	FRONT FENDER ADVERTISEMENT (SN)	CUT	100.00	100.00
1	FRONT DOOR ADVERTISEMENT (SN)	CUT	100.00	100.00
1	REAR DOOR ADVERTISEMENT (SN)	CUT	100.00	100.00
1	REAR FENDER ADVERTISEMENT (SN)	TORN	100.00	100.00
			555.00	555.00
	<u>LABOUR</u>			
	PANEL BEATING.		750.00	560.00
	SPRAY PAINTING.		1,000.00	750.00
	TUFF COAT.	NOT NECESSARY	120.00	-
	CHECK LIGHTING.		50.00	30.00
			1,920.00	1,340.00
	GRAND TOTAL		6,617.96	3,355.24





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,650.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC21001749/T1tf3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser