



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6620E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	458.60	-
1	REAR BUMPER UNDER SIDE COVER LH	TO REPAIR SEE LABOUR	232.00	-
2	REAR BUMPER SIDE RETAINER LH / RH	NOT NECESSARY	112.70	-
1	REAR WHEEL RIM LH	TO REPAIR SEE LABOUR	1,555.00	-
10	REAR BUMPER CLIP	NOT NECESSARY	22.00	-
	LESS 25% DISCOUNT		-595.08	-
			1,785.22	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
1	BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			185.70	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR BUMPER UNDER SIDE COVER LH AND REAR WHEEL RIM LH.		540.00	350.00
	SPRAY PAINTING CHARGE.		600.00	300.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,260.00	680.00
GRAND TOTAL			3,230.92	680.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				680.00

Report Ref No. NS/INC21001750/T1vf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.