

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001751/UQD3Q2
Date: 22/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30826219000
Claimant Vehicle No :	SKX8207L	Insured Vehicle No :	YM9241Y
Date of Loss:	01/02/2021	Nature of Claim:	TP
		Claim No:	SNM21D200592/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX8207L		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2210407A
Reg. Date:	29/12/2015 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1530761
Colour:	Blue	Odometer:	85624 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,375.55	3,916.89	4,458.66	53.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,460.00	840.00	36.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,675.55	5,376.89	5,298.66	49.63
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	10,675.55	4,300.00	6,375.55	59.72

INSPECTION

Date of Assignment:	10/02/2021	
Date Inspected:	05/02/2021	Inspected At:
		Autobay Pte Ltd (kaki Bukit) (HQ) 1 KAKI BUKIT AVE 6, #02-11 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2021)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX8207L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented/Buckled	690.00 F	*685.20 FL
2	1		*BONNET LOCK	Not Necessary	55.00 F	*- FL
3	1		*BONNET LOCK CABLE	Not Necessary	35.00 F	*- FL
4	2		*BONNET HINGES	Not Necessary	80.00 F	*- FL
5	1		*BONNET INSULATOR	Not Necessary	195.00 F	*- FL
6	11		*BONNET INSULATOR CLIPS	Not Necessary	48.40 F	*- FL
7	1		*BONNET GARNISH	Not Necessary	120.00 F	*- FL
8	1		*FRONT FENDER LH	Bent	680.00 F	*622.70 FL
9	1		*FRONT FENDER WHEEL ARCH GARNISH LH	Torn	483.00 F	*483.00 FL
10	1		*FRONT INNERSHIELD LH	Not Necessary	87.50 F	*- FL
11	1		*SET FRONT INNERSHIELD CLIPS LH	Necessary	44.00 F	*35.00 FL
12	1		*FRONT BUMPER	Distorted	675.00 F	*641.60 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	695.00 F	*588.20 FL
14	1		*FRONT BUMPER BEAM	Not Necessary	280.00 F	*- FL
15	1		*FRONT BUMPER SPONGE	Torn	215.00 F	*195.20 FL
16	1		*FRONT BUMPER BRACKET LH	Not Necessary	145.00 F	*- FL
17	1		*FRONT GRILLE	Cracked	550.00 F	*461.20 FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	44.00 F	*35.00 FL
19	6		*FRONT GRILLE CLIPS	Not Necessary	26.40 F	*- FL
20	1		*FRONT GRILLE LOGO	Not Necessary	78.00 F	*- FL
21	1		*FRONT SUPPORT PANEL TOP	Repair	485.00 F	*- FL
22	1		*FRONT HEADLAMP LH	Cracked	520.00 F	*520.00 FL
23	1		*FRONT HEADLAMP WITH LOWER BRACKETS LH	Not Necessary	32.00 F	*- FL
24	1		*FRONT HEADLAMP SIDE GARNISH LH	Not Necessary	80.00 F	*- FL
25	1		*FOG LAMP COVER LH	Scratched	85.00 F	*85.00 FL
26	1		*AIR CLEANER	Not Necessary	675.00 F	*- FL
27	1		*AIR DUCT	Not Necessary	145.00 F	*- FL
28	1		*FRONT NUMBER PLATE WITH HOLDER	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,288.30	4,352.10
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	435.21
+ Margin on L,N Items 15.00/0.00% (\$)	1,087.25	0.00
Total Parts (\$)	8,375.55	3,916.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL WIRING SYSTEMS	New	80.00	20.00
2	TO SPRAY RUST PROOFING	New	120.00	60.00
3	TO RESPRAY PAINTING & ETC	New	1,200.00	800.00
4	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	900.00	580.00
Gross Labour Cost (\$\$)			2,300.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >