



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 8804B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RR BUMPER	DENTED / CRACKED	589.00	589.00
2	RR BUMPER SIDE RETAINER R/L @\$42.00	REFIT	84.00	-
1	RR FENDER RH	DENTED / DISTORTED	616.00	616.00
1	RR WINDSCREEN TOP MOULDING	NECESSARY	28.00	28.00
1	RR WINDSCREEN BOTTOM MOULDING	NECESSARY	146.00	146.00
1	RR BRAKE DRUM RH	SERVICEABLE	282.00	-
1	RR TRAILING ARM RH	SERVICEABLE	378.00	-
1	RR LOWER ARM RH	SERVICEABLE	132.00	-
1	RR CONTROL ARM RH	SERVICEABLE	115.00	-
1	RR STAY ARM RH	SERVICEABLE	86.00	-
1	RR WHEEL HUB ASSY RH	SERVICEABLE	398.00	-
1	RR FENDER INNER PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-285.40	-137.90
			<b>2,568.60</b>	<b>1,241.10</b>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	RR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	RR FENDER PANEL SEALANT RH (SN)	NECESSARY	50.00	30.00
1	RR SPORT RIM RH (SN)	DENTED / DEFACED	400.00	300.00
1	RR TYRE RH (SN)	SERVICEABLE	280.00	-
1	RR SUSPENSION COILOVER BC BR TYRE (SN)	SERVICEABLE	450.00	-
1	BOT BRAKE FLUID (SN)	SERVICEABLE	20.00	-
			<b>1,250.00</b>	<b>370.00</b>
<b><u>LABOUR</u></b>				
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS (INCLUDE REMOVE ROOF LINING).		100.00	50.00
	TO REMOVE AND REINSTALL REAR WINDSCREEN FOR NECESSARY REPAIRS.		120.00	120.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, CHECK AND REPLACE RHR UNDERCARRIAGE PARTS. (INCLUDE FLUSH AND BLEED BRAKES SYSTEM).	NOT NECESSARY	200.00	-
	TO CONDUCT WHEEL ALIGNMENT (2X).		120.00	60.00
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR FENDER INNER PANEL RH.		800.00	660.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		600.00	400.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		50.00	30.00
			1,990.00	1,320.00
	<b>GRAND TOTAL</b>		<b>5,808.60</b>	<b>2,931.10</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,350.00</b>
---	--	--	--	-----------------

Report Ref No. CS3/LPC20011905/Etf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.