

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21001757/UQD3Q2  
**Date:** 05/03/2021

### REFERENCE

|                                                                 |                               |                                   |
|-----------------------------------------------------------------|-------------------------------|-----------------------------------|
| Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: DMCVSNW00063742000 |                                   |
| Claimant Vehicle No : SJA9095T                                  | Insured Vehicle No : GZ8090S  |                                   |
| Date of Loss: 02/02/2021                                        | Nature of Claim: TP           | Claim No: SNM21D200920/C02.THAMYL |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                                                      |                          |
|------------------------------------------------------|--------------------------|
| Reg No: <b>SJA9095T</b>                              |                          |
| Make & Model: TOYOTA WISH, 1.8 (A)                   | Engine No: 1ZZ2921156    |
| Reg. Date: 26/12/2007 (Man. Year: 2007)              | Chassis No: ZNE100368656 |
| Colour: Silver                                       | Odometer: 263747 km      |
| Engine Capacity: 1794 cc                             |                          |
| Market Value/New Car Price: N/A                      |                          |
| Sum Insured (S\$): <b>Market Value/New Car Price</b> |                          |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                                 |                                |
|---------------------------------|--------------------------------|
| Front Tyre Size: 195/65 R15     | Rear Tyre Size: 195/65 R15     |
| Front Left Side: Yokohama 5 mm  | Rear Left Side: Yokohama 5 mm  |
| Front Right Side: Yokohama 5 mm | Rear Right Side: Yokohama 5 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                    | 9,817.25         | 2,199.72        | 7,617.53         | 77.59        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 3,100.00         | 1,430.00        | 1,670.00         | 53.87        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>12,917.25</b> | <b>3,629.72</b> | <b>9,287.53</b>  | <b>71.90</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>2,900.00</b> |                  |              |
| <b>Nett Amount (S\$)</b>                 | <b>12,917.25</b> | <b>2,900.00</b> | <b>10,017.25</b> | <b>77.55</b> |

### INSPECTION

|                                      |               |                                                                                   |
|--------------------------------------|---------------|-----------------------------------------------------------------------------------|
| Date of Assignment: 18/02/2021       |               |                                                                                   |
| Date Inspected: 05/02/2021           | Inspected At: | PKS Automotive Pte Ltd (HQ)<br>8 Kaki Bukit Avenue 4 #01 – 52<br>Singapore 415875 |
| Estimated Period of Repair: 4.0 days |               |                                                                                   |

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                       |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 03 Mar 2021)         |
| <b>Parts:</b>        | M1-MPV                                                                                                                                                                       | TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                     |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJA9095T)                                                                                                                                    |                                                       |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                       |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                       |

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *FRONT BUMPER                 | Distorted     | 581.00 FL   | *581.00 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE COVER LH   | Not Necessary | 53.00 FL    | *- FL      |
| 3   | 1   |          | *FRONT BUMPER SIDE COVER RH   | Not Necessary | 53.00 FL    | *- FL      |
| 4   | 2   |          | *FRONT BUMPER RETAINER        | Not Necessary | 126.00 FL   | *- FL      |
| 5   | 1   |          | *FRONT BUMPER REINFORCEMENT   | Dented        | 318.00 FL   | *287.10 FL |
| 6   | 1   |          | *FRONT BUMPER SPONGE          | Torn          | 161.00 FL   | *161.00 FL |
| 7   | 1   |          | *FRONT BUMPER LOWER GRILLE    | Not Necessary | 183.00 FL   | *- FL      |
| 8   | 1   |          | *FRONT GRILLE ASSY            | Cracked       | 172.00 FL   | *172.00 FL |
| 9   | 1   |          | *FRONT SUPPORT PANEL          | Repair        | 711.00 FL   | *- FL      |
| 10  | 1   |          | *FRONT HEADLAMP LH            | Not Necessary | 781.00 FL   | *- FL      |
| 11  | 1   |          | *FRONT HEADLAMP RH            | Cracked       | 781.00 FL   | *689.10 FL |
| 12  | 1   |          | *FRONT FENDER LH              | Not Necessary | 681.00 FL   | *- FL      |
| 13  | 1   |          | *FRONT FENDER RH              | Not Necessary | 681.00 FL   | *- FL      |
| 14  | 1   |          | *FRONT FENDER INNER SHIELD LH | Not Necessary | 181.00 FL   | *- FL      |
| 15  | 1   |          | *FRONT FENDER INNER SHIELD RH | Not Necessary | 181.00 FL   | *- FL      |
| 16  | 1   |          | *WIPER WASHER TANK            | Not Necessary | 171.00 FL   | *- FL      |
| 17  | 1   |          | *BONNET                       | Dented        | 721.00 FL   | *695.10 FL |
| 18  | 1   |          | *BONNET CHROME STRIP          | Cracked       | 281.00 FL   | *281.00 FL |
| 19  | 1   |          | *BONNET LOCK                  | Not Necessary | 213.00 FL   | *- FL      |
| 20  | 1   |          | *BONNET INSULATOR             | Not Necessary | 289.00 FL   | *- FL      |
| 21  | 2   |          | *BONNET HINGE                 | Not Necessary | 110.00 FL   | *- FL      |
| 22  | 1   |          | *AIRCON CONDENSER             | Not Necessary | 1,817.00 FL | *- FL      |
| 23  | 1   |          | *AIRCON SUCTION PIPE-LOW      | Not Necessary | 561.00 FL   | *- FL      |
| 24  | 1   |          | *AIRCON SUCTION PIPE-HIGH     | Not Necessary | 568.00 FL   | *- FL      |
| 25  | 1   |          | *RADIATOR                     | Not Necessary | 1,317.00 FL | *- FL      |
| 26  | 1   |          | *RADIATOR COWLING             | Not Necessary | 561.00 FL   | *- FL      |
| 27  | 1   |          | *RADIATOR FAN MOTOR           | Not Necessary | 381.00 FL   | *- FL      |
| 28  | 1   |          | *RADIATOR FAN BLADE           | Not Necessary | 48.00 FL    | *- FL      |
| 29  | 1   |          | *RADIATOR EXPANSION TANK      | Not Necessary | 181.00 FL   | *- FL      |
| 30  | 1   |          | *SET FRONT NUMBER PLATE       | Not Necessary | 40.00 FS    | *- FS      |
| 31  | 1   |          | *SET FRONT BUMPER CLIP        | Necessary     | 30.00 FS    | *30.00 FS  |
| 32  | 1   |          | *SET BONNET INSULATOR CLIP    | Not Necessary | 20.00 FS    | *- FS      |
| 33  | 1   |          | *SET FRONT GRILLE CLIP        | Necessary     | 20.00 FS    | *20.00 FS  |
| 34  | 1   |          | *BOT COOLANT                  | Not Necessary | 60.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>13,033.00</b> | <b>2,916.30</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 3,215.75         | 716.58          |
| <b>Total Parts (\$\$)</b>                                  | <b>9,817.25</b>  | <b>2,199.72</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                                            | Lab.Type | Repairer's      | Amount          |
|--------------------------|--------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>      |                                                        |          |                 |                 |
| 1                        | CHECK FRONT WIRING AND LIGHTNING SYSTEM                | New      | 80.00           | 30.00           |
| 2                        | REMOVE,RENEW CONDENSER AND TOP UP GAS                  | New      | 150.00          | 0.00            |
| 3                        | REMOVE,RENEW RADIATOR AND TO UP COOLANT                | New      | 150.00          | 0.00            |
| 4                        | PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS | New      | 1,200.00        | 600.00          |
| 5                        | SPRAY PAINTING ON AFFECTED AREAS                       | New      | 1,400.00        | 800.00          |
| 6                        | APPLY ANTI RUST ON AFFECTED AREAS                      | New      | 120.00          | 0.00            |
| Gross Labour Cost (\$\$) |                                                        |          | <b>3,100.00</b> | <b>1,430.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >