

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21001761/R1BA3Q2

Date: 15/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLP2039A	Insured Vehicle No :	SLU3089Y
Date of Loss:	04/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000536

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP2039A	Engine No:	CZC143817
Make & Model:	VOLKSWAGEN GOLF, 1.4 (A)	Chassis No:	WVWZZZAUZH072975
Reg. Date:	29/05/2017 (Man. Year: 2016)	Odometer:	61743 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,820.60	1,639.54	1,181.06	41.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,120.00	3,560.00	62.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,500.60	3,759.54	4,741.06	55.77
+ GST 7.00/7.00% (S\$)	595.04	263.17	331.87	55.77
Nett Amount (S\$)	9,095.64	4,022.71	5,072.93	55.77
+ Car Rental (3.0 x S\$112.15/day + 7.00% GST) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,390.16		

INSPECTION

Date of Assignment:	05/02/2021	
Date Inspected:	09/02/2021 Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2021)
Parts:	144	VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP2039A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,251.35 FS	*1,251.35 FS
2	1		*REAR DIFFUSOR SATIN BLACK	Serviceable	328.37 FS	*- FS
3	4		*RIVET	Necessary	4.56 FS	*4.56 FS
4	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
5	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
6	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
7	1		*SENSOR BRACKET	Necessary	14.51 FS	*14.51 FS
8	1		*2K-PLASTIC ADHESIVE	Necessary	78.91 FS	*78.91 FS
9	1		*BONDING AGENT FOR PLASTIC	Necessary	62.81 FS	*62.81 FS
10	1		*BUMPER REINFORCEMENT	Serviceable	626.36 FS	*- FS
11	1		*ATTACHMENT STRIP RR CTR BRACKET	Serviceable	67.89 FS	*- FS
12	1		*GUIDE PIECE LHR TAILLIGHT BRACKET	Serviceable	39.22 FS	*- FS
13	1		*GUIDE PIECE LHR SIDE BRACKET	Serviceable	39.22 FS	*- FS
14	1		*NUMBER PLATE	Serviceable	80.00 FS	*- FS
15	1		*EXHAUST PIPE TIPS	Missing	183.87 FS	*183.87 FS
					Total Parts (\$\$)	2,820.60 1,639.54

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINTING	New	2,400.00	800.00
Gross Labour Cost (\$\$)			5,680.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >