

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001762/T1PA3Q2
Date: 12/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800082855
Claimant Vehicle No :	SHA2399L	Insured Vehicle No :	SMC2036P
Date of Loss:	03/02/2021	Nature of Claim:	TP
		Claim No:	6885530720SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2399L	Engine No:	2ZRS055312
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDEB3FU303560981
Reg. Date:	29/06/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,839.63	453.96	5,385.67	92.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	630.00	850.00	57.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,319.63	1,083.96	6,235.67	85.19
Approved Total (Overridden) (S\$)		850.00		
(S\$)	7,319.63	850.00	6,469.63	88.39
+ GST 7.00/7.00% (S\$)	512.37	59.50	452.87	88.39
Nett Amount (S\$)	7,832.00	909.50	6,922.50	88.39
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.40/day) (S\$)		501.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,613.10		
Global Sum Settlement (S\$)		1,600.00		

INSPECTION

Date of Assignment: 05/02/2021

Date Inspected: 05/02/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

5/12/2021

Adjuster Report

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER SIDE BRACKET /LH	Not Necessary	82.30 FL	*- FL
2	1		*FRT BUMPER COVER	Cracked	499.90 FL	*499.90 FL
3	1		*FRT BUMPER REINFORCEMENT	Not Necessary	696.40 FL	*- FL
4	1		*FRT BUMPER CENTRE GRILLE	Not Necessary	301.90 FL	*- FL
5	1		*FRT BUMPER LOWER GRILLE	Not Necessary	166.90 FL	*- FL
6	1		*FRT BUMPER TOW COVER	Cut	28.38 FL	*28.38 FL
7	1		*FRT GRILLE EMBLEM	Not Necessary	88.00 FL	*- FL
8	1		*FRT FENDER LH	Not Necessary	945.30 FL	*- FL
9	1		*FRT BUMPER EMBLEM	Not Necessary	86.50 FL	*- FL
10	1		*FRT FENDER SHIELD LH	Not Necessary	198.50 FL	*- FL
11	1		*FRT RUNNING DAYLIGHT LH	Not Necessary	920.00 FL	*- FL
12	1		*HEADLAMP SUPPORT PANEL LH	Not Necessary	240.10 FL	*- FL
13	1		*HEAD LAMP LH	Not Necessary	3,455.00 FL	*- FL
14	1		*FRT BUMPER SIDE RETAINER /LH	Deformed	77.00 FL	*77.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,786.18	605.28
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,946.55	151.32
Total Parts (\$\$)	5,839.63	453.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING CHARGE	New	600.00	250.00
3	CHECK WIRING	New	60.00	30.00
4	TOWING FEE	New	60.00	0.00
5	TUFF COAT	New	60.00	0.00
Gross Labour Cost (S\$)			1,480.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >