

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/FWD21001764/R1PA3Q2**Date:** 19/08/2021REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00008341-03  
**Claimant Vehicle No :** SJW5489B **Insured Vehicle No :** SJK8478B  
 Date of Loss: 02/02/2021 Nature of Claim: TP Claim No: 1202100000690

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW5489B**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4924854  
 Reg. Date: 03/09/2009 (Man. Year: 2009) Chassis No: MR053ZEE106153042  
 Colour: Grey Odometer: 241673 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm  
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,955.42	1,877.02	1,078.40	36.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,140.00	470.00	29.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,565.42</b>	<b>3,017.02</b>	<b>1,548.40</b>	<b>33.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,565.42</b>	<b>2,400.00</b>	<b>2,165.42</b>	<b>47.43</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 04/02/2021  
 Date Inspected: 08/02/2021 Inspected At: Xinya Auto Services Pte Ltd (HQ)  
 Blk 1002, #01-75, Bukit Merah Lane 3  
 Singapore 159719  
 Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2021)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJW5489B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	581.70 FL	*581.70 FL
2	1		*FRONT BUMPER RETAINER RH	Necessary	144.30 FL	*144.30 FL
3	1		*FRONT FENDER RH	Bent	712.90 FL	*712.90 FL
4	1		*FRONT FENDER COWLING RH	Serviceable	199.85 FL	*- FL
5	1		*HEADLAMP RH	Scratched	608.80 FL	*608.80 FL
6	1		*TYRE RIM	Scratched	447.38 FS	*300.00 FS
7	10		*BUMPER /FENDER CLIPS	Necessary	55.00 FL	*55.00 FL
8	1		*BONNET	Repair	1,041.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,791.43</b>	<b>2,402.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	836.01	525.68
<b>Total Parts (\$\$)</b>	<b>2,955.42</b>	<b>1,877.02</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE FRONT BUMPER ,FENDER ,HEADLAMP AND PANEL BEAT & ALIGN	New	800.00	400.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER & BONNET AND OTHER AFFECTED AREA	New	600.00	600.00
3	TO CHECK & RECTIFY WIRING AND FOCUS HEADLAMP	New	80.00	30.00
4	TO REPLACE TYRE RIM AND BALANCING	New	50.00	50.00
5	TO COMPUTER WHEEL ALIGNMENT	New	80.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>1,610.00</b>	<b>1,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >