

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001795/EVD3Q2

Date: 09/03/2021

REFERENCE

Insured/Claimant:	TAN KENG BOO	Policy No:	1900149633	
Date of Loss:	05/02/2021	Nature of Claim:	OD	Claim No: 0324726436SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN6181T		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11BD7746
Reg. Date:	21/08/2019 (Man. Year: 2019)	Chassis No:	GF7W0601723
Colour:	Blue	Odometer:	24787 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$104,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R18	Rear Tyre Size:	205/55R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,561.00	1,428.29	5,132.71	78.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,785.00	2,730.00	3,055.00	52.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,346.00	4,158.29	8,187.71	66.32
+ GST 7.00/7.00% (\$\$)	864.22	291.08	573.14	66.32
Nett Amount (\$\$)	13,210.22	4,449.37	8,760.85	66.32

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 08/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRKT,R/BMPR FACE SIDE,RH	Broken	12.00 F	*12.00 FL
2	1		*BRKT,R/BMPR FACE SIDE,LH	Broken	12.00 F	*12.00 FL
3	1		*FACE,RR BUMPER	Dented	807.00 F	*807.00 FL
4	1		*REINFORCEMENT,RR BUMPER,LH	Not Necessary	79.00 F	*- FL
5	1		*REINFORCEMENT,RR BUMPER,RH	Not Necessary	79.00 F	*- FL
6	1		*EXTENSION,RR BUMPER	Dented	292.00 F	*292.00 FL
7	1		*MOULDING,RR BUMPER,RH	Necessary	106.00 F	*106.00 FL
8	1		*MOULDING,RR BUMPER,LH	Necessary	106.00 F	*106.00 FL
9	1		*PANEL,RR END	Not Necessary	324.00 F	*- FL
10	1		*PANEL,RR END,INR LH	Not Necessary	146.00 F	*- FL
11	1		*PANEL,RR END,INR RH	Not Necessary	146.00 F	*- FL
12	1		*SHIELD,RR WHEEL,RR RH	Not Necessary	22.00 F	*- FL
13	1		*SHIELD,RR WHEEL,RR LH	Not Necessary	22.00 F	*- FL
14	1		*MARK,OUTLANDER	Necessary	95.00 F	*95.00 FL
15	1		*TRIM RR END	Not Necessary	113.00 F	*- FL
16	1		*REFLECTOR,TAIL LAMP,RH	Not Necessary	100.00 F	*- FL
17	1		*REFLECTOR,TAIL LAMP,LH	Not Necessary	100.00 F	*- FL
18	1		*LAMP ASSY,COMB,RR LH	Not Necessary	600.00 F	*- FL
19	1		*LAMP ASSY,COMB,RR RH	Not Necessary	600.00 F	*- FL
20	1		*BUZZER,KEYLESS OPERATIO,RR	Broken	91.00 F	*91.00 FL
21	1		*ANT,KEYLESS OPERATION,RR	Broken	96.00 F	*96.00 FL
22	1		*MUFFLER,EXHAUST MAIN	Not Necessary	579.00 F	*- FL
23	1		*PIPE,EXHAUST,CTR	Not Necessary	1,814.00 F	*- FL
24	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
25	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
26	1		*MOULDING,RR WHEEL ARCH,LH (Supplementary)	Necessary	160.00 F	*160.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,561.00	1,837.00
- List Item Discount on L Items 0.00/23.00% (\$\$)	0.00	408.71
Total Parts (\$\$)	6,561.00	1,428.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER,REAR END PANEL,REPAIR TAILGATE,REAR FENDER LH,REAR FENDER RH	New	2,250.00	675.00
2	SPRAY PAINT FOR REAR BUMPER,TAILGATE,REAR FENDER RH & LH,REAR END PANEL	New	1,750.00	1,050.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	-
7	RENEW REAR EXHAUST PIPE	New	480.00	0.00
8	REPAIR REAR END PANEL (Supplementary)	New	225.00	225.00
9	RESPRAY REAR END PANEL (Supplementary)	New	350.00	350.00
10	SUPPLY ONE SET OF REVERSE SENSOR (Supplementary) (Broken)	New	220.00	220.00
Gross Labour Cost (\$\$)			5,785.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >