



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GR 3855C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOT COVER	TO REPAIR SEE LABOUR	2,162.70	-
1	BOOT COVER EMBLEM	NECESSARY	84.50	68.10
1	REAR WINDSCREEN INNER SEAL	NOT NECESSARY	60.00	-
1	REAR BUMPER	TORN	355.60	355.60
1	REAR BUMPER BRACKET	CRACKED / TWISTED	35.60	35.60
1	TAILLAMP ASSY-O/S	BROKEN	367.80	367.80
1	REAR CORNER GARNISH O/S	DISTORTED	101.00	101.00
1	HIACE STICKER	NECESSARY	49.20	49.20
1	1250KG STICKER	NECESSARY	36.80	36.80
1	REAR CORNER GARNISH BRACKET - RH	CRACKED	35.20	35.20
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	1,375.00	-
	LESS 25% DISCOUNT		-	-262.33
			4,663.40	786.97
<b>LABOUR</b>				
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO RESRAY ACCIDENT AFFECTED PARTS.		1,200.00	500.00
	TO REMOVE & REFIT REAR O/S FENDER GLASS.	NOT NECESSARY	180.00	-
	PANEL BEATING, CUT AND REWELD REAR O/S FENDER. INCLUSIVE OF THE REPAIR OF BOOT COVER.		1,600.00	600.00
			3,160.00	1,100.00
<b>GRAND TOTAL</b>			<b>7,823.40</b>	<b>1,886.97</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,886.97</b>

Report Ref No. CS/LPC21001801/Uqd3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.