



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2106489

INV Date 16/09/2021

Reference CC4/LPC21001808/Dps3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 2666R

Insured Veh. GBE 7215B

Claim No. 20/21/21/VC00/024208

Policy No. Z19VC05001887

Accident Date 05/02/2021

Inspection Date 08/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21001808/Dps3q2	
			Date: 16/09/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 7215B	Veh. Inspected	SHA 2666R	
Policy No.	Z19VC05001887	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024208	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	08/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU203562950	Colour	BLUE	
Odometer	452682 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/02/2021	Inspection Date	08/02/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2666R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TRUNK LID COVER	DENTED / BENT	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	BENT / DAMAGED	457.90	457.90
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	254.40	-
1	BOOT LID TRIMBOARD ,CENTRE	NOT NECESSARY	159.60	-
1	BOOT LID TRIMBOARD SIDE (LH)	NOT NECESSARY	92.50	-
1	BOOT LID TRIMBOARD REAR	NOT NECESSARY	124.80	-
1	BOOT HANDLE	NOT NECESSARY	31.80	-
1	REAR TRUNK LID RUBBER	DEFORMED	365.20	365.20
1	REAR TRUNK LID GLASS (BLACK COLOR)	SHATTERED	969.70	969.70
1	BOARD ASSY ,BACK DOOR TRIM	NOT NECESSARY	354.40	-
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	CRACKED / BROKEN	896.30	896.30
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR TRUNK LID STRIKER	TO REPAIR SEE LABOUR	98.70	-
1	SPOILERSUB-ASSY ,REAR	CRACKED / BROKEN	953.70	953.70
1	REAR BUMPER	CRACKED / DISTORTED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	BENT / DENTED	318.80	318.80
1	REAR BUMPER LOWER COVER	TORN	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	82.70	-
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE CLIP	NOT NECESSARY	25.00	-
2	REAR BUMPER UPPER STOPPER (LH) @\$76.40	NOT NECESSARY	152.80	-
1	SEAL ,REAR BUMPER SIDE ,LH	NOT NECESSARY	148.40	-
1	REAR BUMPER UNDER SIDE COVER (LH)	NOT NECESSARY	232.00	-
1	ARM SUB-ASSY ,REAR BUMPER (LH)	MTG CRACKED	139.60	139.60
1	TAIL LAMP ASSY (UPPER) (N/S)	BROKEN	557.90	557.90

Report Ref No. CC4/LPC21001808/Dps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP ASSY (LOWER) (N/S)	BROKEN	548.40	548.40
1	TAIL LAMP QUARTER PANEL	DENTED	216.00	216.00
1	TAIL LAMP SIDE COVER (N/S)	CUT / DISTORTED	256.00	256.00
1	REAR TAILLAMP GUIDE -WHITE	NOT NECESSARY	95.30	-
1	REAR END PANEL	DENTED	602.10	602.10
1	REAR END PANEL GARNISH	DEFORMED	165.80	165.80
1	REAR WIRING ASSY	NOT NECESSARY	582.40	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	NOT NECESSARY	101.40	-
1	REAR FIBER TOOL BOX TRIM (LH)	NOT NECESSARY	598.00	-
1	REAR FIBER TOOL BOX CENTER	NOT NECESSARY	186.20	-
1	SPARE TYRE LOCK NUT	NOT NECESSARY	88.40	-
1	SPARE TYRE LOCK NUT BRACKET	NOT NECESSARY	113.50	-
1	SPARE TYRE SIDE PANEL (LH)	NOT NECESSARY	196.50	-
1	REAR EXHAUST PIPE	NOT NECESSARY	1,163.40	-
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	40.70	-
1	REAR EXHAUST PIPE INSULATOR	NOT NECESSARY	314.60	-
	LESS 20% DISCOUNT		-2,958.24	-
	LESS 25% DISCOUNT		-	-2,193.33
			11,832.96	6,579.97
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE CAMERA ASSY (SN)	NOT NECESSARY	380.00	-
1	REAR TRUNK LOWER W/S MOULDING (SN)	NECESSARY	180.00	180.00
1	REAR LOWER W/S SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR WINDSCREEN MOULDING (SN)	NECESSARY	160.00	160.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
			1,047.70	667.70
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TRUNK LID STRIKER .		1,800.00	900.00

Report Ref No. CC4/LPC21001808/Dps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.		1,400.00	800.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX REAR WINDSCREEN GLASS .		240.00	80.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00
	REMOVE/REFIX FUEL TANK .	NOT NECESSARY	80.00	-
	REMOVE/REFIX EXHAUST PIPE .	NOT NECESSARY	80.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	-
			4,550.00	1,890.00
GRAND TOTAL			17,430.66	9,137.67

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,300.00
---	--	--	--	-----------------

Report Ref No. CC4/LPC21001808/Dps3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 2666R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 2666R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 2666R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

