

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001815/T1QD3Q2
Date: 19/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00011552100
Claimant Vehicle No :	SGG4807T	Insured Vehicle No :	GBL5005S
Date of Loss:	04/02/2021	Nature of Claim:	TP
		Claim No:	SNM21D200706/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG4807T	Engine No:	K24A63000062
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRB18506C200062
Reg. Date:	15/05/2006 (Man. Year: 2005)	Odometer:	217335 km
Colour:	Beige		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,791.90	6,938.60	5,853.30	45.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	2,570.00	1,300.00	33.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,661.90	9,508.60	7,153.30	42.93
Approved Total (Overridden) (S\$)		7,600.00		
Nett Amount (S\$)	16,661.90	7,600.00	9,061.90	54.39

INSPECTION

Date of Assignment:	08/02/2021	
Date Inspected:	08/02/2021 Inspected At:	Huat Hock Motor Workshop (HQ) BLK 3012 BEDOK NORTH AVE 4, #01-2054 BEDOK INDUSTRIAL PARK E Singapore 1648
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

3/19/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2021)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGG4807T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,257.40 F	*1,030.50 FL
2	2		*REAR BOOTLID DAMPER	Repair	310.60 F	*- FL
3	1		*REAR BOOTLID LOCK	Bent	219.30 F	*219.30 FL
4	1		*REAR BOOTLID WEATHERSTRIP	Twisted	151.60 F	*151.60 FL
5	1		*REAR BOOTLID CAMERA	Not Necessary	380.00 F	*- FL
6	1		*REAR BOOTLID TRIM BOARD	Deformed	212.00 F	*212.00 FL
7	2		*REAR BOOTLID LH & RH GARNISH	Not Necessary	152.40 F	*- FL
8	1		*REAR BOOTLID OUTER GARNISH	Cracked	406.10 F	*406.10 FL
9	1		*REAR BOOTLID WINDSCREEN	Cracked	1,203.50 F	*1,203.50 FL
10	1		*REAR BOOTLID WINDSCREEN MOULDING	Necessary	138.00 F	*138.00 FL
11	1		*REAR BOOTLID LOGO	Necessary	37.40 F	*37.40 FL
12	1		*REAR BOOTLID EMBLEM	Necessary	45.50 F	*45.50 FL
13	1		*REAR BOOTLID TRIM BOARD CLIP	Necessary	38.00 F	*38.00 FL
14	1		*REAR BOOTLID NUMBER PLATE LAMP	Cracked	62.10 F	*62.10 FL
15	1		*REAR BUMPER	Deformed	896.00 F	*896.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Not Necessary	46.40 F	*- FL
17	2		*REAR BUMPER SIDE CHROME	Cracked	130.60 F	*130.60 FL
18	1		*REAR BUMPER REVERSE SENSOR (4 Pcs)	Not Working	380.00 F	*250.00 FL
19	1		*REAR BUMPER CLIP	Necessary	38.00 F	*38.00 FL
20	1		*REAR BUMPER BEAM	Bent	265.40 F	*197.00 FL
21	2		*REAR BUMPER BRACKET LH & RH	Not Necessary	42.60 F	*- FL
22	1		*REAR BOOTLID WIPER MOTOR	Bent	228.60 F	*228.60 FL
23	1		*REAR BOOTLID WIPER ARM	Broken	46.00 F	*46.00 FL
24	1		*REAR BOOTLID WIPER RUBBER	Missing	44.00 F	*44.00 FL
25	1		*REAR BOOTLID ARM COVER	Missing	12.90 F	*12.90 FL
26	1		*REAR BUMPER TOWING COVER	Not Necessary	32.20 F	*- FL
27	1		*REAR TAILLAMP LH	Cracked	385.60 F	*385.60 FL
28	1		*REAR TAILLAMP RH	Cracked	385.60 F	*385.60 FL
29	1		*REAR FENDER LH	Repair	832.20 F	*- FL
30	1		*REAR FENDER RH	Repair	832.20 F	*- FL
31	1		*REAR END PANEL	Bent	545.90 F	*545.90 FL
32	1		*REAR END PANEL TOP GARNISH	Deformed	251.50 F	*251.50 FL
33	1		*REAR SPARE TYRE PANEL	Repair	585.90 F	*- FL
34	1		*REAR SPARE TYRE BOARD	Cracked	254.10 F	*254.10 FL
35	1		*REAR SPARE TYRE	Not Necessary	280.00 F	*- FL
36	1		*REAR SPARE TYRE NUT & BOLT	Not Necessary	45.10 F	*- FL
37	1		*REAR RH FENDER GARNISH INNER	Deformed	485.60 F	*485.60 FL
38	1		*REAR LH FENDER GARNISH INNER	Deformed	485.60 F	*485.60 FL
39	1		*REAR RH FENDER GARNISH CLIP	Necessary	38.00 F	*38.00 FL
40	1		*REAR LH FENDER GARNISH CLIP	Necessary	38.00 F	*38.00 FL
41	1		*REAR TAILGATE SEALANT	Necessary	120.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

3/19/2021

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*NO PLATE & CASING	Bent	50.00 FS	*45.00 FS
43	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
44	1		*REAR BOOTLID THIRD BRAKE LAMP	Cracked	215.00 F	*150.00 FL
45	1		*REAR BOOTLID NUMBER PLATE LAMP HOLDER	Cracked	85.00 F	*85.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					12,791.90	8,637.00
- List Item Discount on L Items 0.00/20.00% (\$)					0.00	1,698.40
Total Parts (\$)					12,791.90	6,938.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS,END PANEL	New	1,400.00	1,000.00
2	TO SPRAY PAINTING ON AFFECTED AREA (BOOTLID,REAR BUMPER,LH & RH FENDER,REAR END PANEL,TYRE PANEL)	New	1,600.00	1,200.00
3	TO SPRAY ANTI-RUST COATING ON EFFECT PANEL	New	120.00	40.00
4	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS BOARDS,GARNISH ETC NECESSARY REPAIR	New	250.00	60.00
5	TO TRANSFER TAILGATE,MECHANISM & COMPONENT	New	120.00	60.00
6	TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	80.00	30.00
7	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE	New	150.00	120.00
8	REMOVE & FIX REAR SENSOR,REAR CAMERA	New	150.00	60.00
Gross Labour Cost (\$\$)			3,870.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >