

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001816/NVF3Q2

Date: 12/04/2021

REFERENCE

Insured/Claimant: KARUPPIAH GANDHI Policy No: 2070143116
Date of Loss: 01/01/2021 Nature of Claim: OD Claim No: 2359311165SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR7180Z**
Make & Model: HONDA CB150R, 149cc Engine No: KC92E1018674
Reg. Date: 05/10/2020 (Man. Year: 2019) Chassis No: MH1KC9217KK023092
Colour: Red Odometer: 2409 km
Engine Capacity: 149 cc
Market Value/New Car Price: S\$10,500.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80 R17 Rear Tyre Size: 130/70 R17
Front Left Side: IRC 4 mm Rear Left Side: IRC 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,341.20	2,517.70	823.50	24.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	550.00	1,390.00	71.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,281.20	3,067.70	2,213.50	41.91
Approved Total (Overridden) (S\$)		2,450.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
Nett Amount (S\$)	4,981.20	2,150.00	2,831.20	56.84

INSPECTION

Date of Assignment: 08/02/2021
Date Inspected: 09/02/2021 Inspected At: Bike Production (HQ)
No 610 Serangoon Road
Singapore 218216
Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*STEERING STEM BEARING	Necessary	90.00 FL	*90.00 FL
2	1		*FRONT FORK STEERING STEM	Serviceable	295.00 FL	*- FL
3	1		*LEFT TAIL COVER	Scratched	145.00 FL	*145.00 FL
4	1		*LEFT REAR SIGNAL	Scratched	125.00 FL	*125.00 FL
5	1		*HEADLAMP FAIRING	Scratched	185.00 FL	*185.00 FL
6	1		*LEFT SIDE FRONT SIGNAL	Scratched	125.00 FL	*125.00 FL
7	1		*RIGHT SIDE FAIRING AEBLEM	Necessary	55.00 FL	*30.00 FL
8	1		*HEADLAMP FAIRING AEBLEM	Necessary	55.00 FL	*30.00 FL
9	1		*LEFT TAIL COVER AEBLEM	Necessary	65.00 FL	*40.00 FL
10	1		*RIGHT SIDE FAIRING	Scratched	225.00 FL	*200.00 FL
11	1		*LEFT SIDE FAIRING AEBLEM	Necessary	55.00 FL	*30.00 FL
12	1		*LEFT SIDE FAIRING	Scratched	225.00 FL	*200.00 FL
13	1		*LEFT BALANCER	Bent	55.00 FL	*55.00 FL
14	1		*CLUTCH LEVER	Scratched	65.00 FL	*65.00 FL
15	1		*LEFT STEERING HANDLE	Bent	185.00 FL	*120.00 FL
16	1		*LEFT REAR FOOTREST HOLDER	Serviceable	155.00 FL	*- FL
17	1		*LEFT REAR FOOTREST	Scratched	75.00 FL	*75.00 FL
18	1		*LEFT VIEW MIRROR	Scratched	115.00 FL	*115.00 FL
19	1		*GEAR PEDAL ASSY	Serviceable	95.00 FL	*- FL
20	1		*LEFT FRONT FOOTREST	Scratched	75.00 FL	*75.00 FL
21	1		*LEFT FRONT FOOTREST HOLDER	Bent	175.00 FL	*130.00 FL
22	1		*IU BRACKET	Bent	45.00 FL	*45.00 FL
23	1		*ERP IU	Grazed	157.00 FS	*157.00 FS
24	1		*LEFT SWITCH ASSY (Supplementary)	Deformed	205.00 FL	*130.00 FL
25	1		*LEFT BLACK FAIRING INNER COVER (Supplementary)	Cracked	185.00 FL	*150.00 FL
26	1		*LEFT SIDE FAIRING GREY COVER (Supplementary)	Deformed	165.00 FL	*165.00 FL
27	1		*HEADLAMP INNER COVER (Supplementary)	Deformed	145.00 FL	*145.00 FL
28	1		*LEFT UPPER FRONT COVER (Supplementary)	Deformed	75.00 FL	*75.00 FL
29	1		*LEFT SIDE COVER LOWER (Supplementary)	Deformed	78.00 FL	*78.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,695.00	2,780.00
- List Item Discount on L Items 10.00/10.00% (S\$)	353.80	262.30
Total Parts (S\$)	3,341.20	2,517.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	0.00
2	REPLACE,REALIGN AND ADJUST ABOVE DAMAGED PARTS,CHECK WIRING AND KIGHTING SYSTEM	New	700.00	300.00
3	TO BALANCE FRONT AND REAR WHEEL RIMS	New	60.00	0.00
4	TO KNOCK,STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
5	TO REMOVE/REFIT,REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	150.00	0.00
6	SPRAY PAINTING	New	400.00	200.00
7	LABOUR FOR SUPPLEMENTARY ITEMS (Supplementary)	New	150.00	50.00
Gross Labour Cost (\$\$)			1,940.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >