

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21001817/BBA3Q2

Date:

16/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100287731

Claimant Vehicle No : PC2078H**Insured Vehicle No :**

SKE348R

Date of Loss: 05/02/2021

Nature of Claim:

TP

Claim No:

5902200852SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC2078H**
 Make & Model: TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)
 Reg. Date: 16/07/2013 (Man. Year: 2013)
 Colour: White
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD2289928
 Chassis No: JTFST22P500016689
 Odometer: 291144 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 15 Rear Tyre Size: 195 15
 Front Left Side: Neuton 6 mm Rear Left Side: Neuton 6 mm
 Front Right Side: Neuton 6 mm Rear Right Side: Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,492.25	9,732.74	12,759.51	56.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,630.00	3,700.00	2,930.00	44.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,122.25	13,432.74	15,689.51	53.87
Approved Total (Overridden) (S\$)		10,750.00		

(S\$)	29,122.25	10,750.00	18,372.25	63.09
+ GST 7.00/7.00% (S\$)	2,038.56	752.50	1,286.06	63.09
Nett Amount (S\$)	31,160.81	11,502.50	19,658.31	63.09
+ Loss of Use (18.0 x S\$120.00/day) (S\$)		2,160.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		200.00		
Nett Liability (S\$)		13,869.95		
Global Sum Settlement (S\$)		13,800.00		

INSPECTION

Date of Assignment: 05/02/2021

Date Inspected: 08/02/2021

Estimated Period of Repair: 10.0 days

Inspected At:

160 SIN MING DRIVE #01-14 SINGAPORE 575722
Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)**Adjuster:** Lim Teow Guan**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	844.50 FL	*707.85 FL
2	1		*BONNET LOGO	Necessary	65.00 FL	*65.00 FL
3	1		*BONNET LOCK	Jammed	181.90 FL	*181.90 FL
4	2		*BONNET HINGE	Not Damaged	246.80 FL	*- FL
5	1		*FRONT BUMPER	Bent	786.30 FL	*541.20 FL
6	1		*FRONT BUMPER BRACKET	Bent	577.10 FL	*271.20 FL
7	2		*FRONT BUMPER SIDE RETAINER	Necessary	151.20 FL	*133.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	392.20 FL	*357.10 FL
9	2		*FRONT BUMPER TOW CAP	Missing	96.00 FL	*50.00 FL
10	1		*FRONT BUMPER LOWER GRILLE	Broken	271.50 FL	*239.50 FL
11	2		*FRONT BUMPER FOG LAMP GARNISH	Broken	176.40 FL	*110.00 FL
12	1		*FRONT GRILLE TOP GARNISH	Broken	781.30 FL	*326.90 FL
13	1		*FRONT GRILLE LOWER GARNISH	No such part	278.60 FL	*- FL
14	1		*FRONT GRILLE BASE	No such part	223.10 FL	*- FL
15	1		*FRONT CORNER PANEL	N/S Dented	549.00 FL	*274.50 FL
16	1		*FRONT SUPPORT PANEL	Bent	571.80 FL	*384.20 FL
17	1		*FRONT SUPPORT PANEL CENTRE BRACKET	Bent	65.30 FL	*65.30 FL
18	1		*FRONT SUPPORT PANEL TOP COVER	No such part	271.60 FL	*- FL
19	1		*FRONT SUPPORT PANEL TOP COVER RUBBER	Torn	121.60 FL	*121.60 FL
20	1		*FRONT WHEEL HOUSE PANEL	Not Damaged	928.10 FL	*- FL
21	1		*FRONT WHEEL HOUSE PANEL INSULATOR	Not Damaged	250.00 FL	*- FL
22	2		*FRONT DOOR	Repair	1,970.80 FL	*- FL
23	2		*FRONT DOOR MOULDING	Not Damaged	524.00 FL	*- FL
24	2		*FRONT DOOR PILLAR	Not Damaged	842.00 FL	*- FL
25	2		*FRONT STEP GARNISH	Not Damaged	376.40 FL	*- FL
26	2		*HEADLAMP	Broken	1,909.60 FL	*1,488.00 FL
27	2		*HEADLAMP LOWER BRACKET	No such part	76.40 FL	*- FL
28	2		*HEADLAMP PANEL	No such part	297.20 FL	*- FL
29	1		*RADIATOR	Broken	1,817.10 FL	*1,596.70 FL
30	1		*RADIATOR FAN COWLING	Broken	542.30 FL	*286.30 FL
31	2		*RADIATOR FAN MOTOR	Not Damaged	708.00 FL	*- FL
32	1		*RADIATOR TOP HOSE	Necessary	210.00 FL	*80.00 FL
33	1		*RADIATOR LOWER HOSE	Necessary	284.60 FL	*80.00 FL
34	1		*A/C CONDENSER	Dented	1,417.50 FL	*1,245.30 FL
35	1		*A/C CONDENSER HIGH PRESSURE PIPE	Not Necessary	298.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*A/C CONDENSER LOWE PRESSURE PIPE	Not Necessary	387.40 FL	*- FL
37	1		*INTERCOOLER	Dented	1,213.60 FL	*1,213.60 FL
38	1		*WIPER WASHER TANK	Broken	188.30 FL	*89.70 FL
39	1		*RADIATOR SPARE TANK	Broken	415.00 FL	*316.10 FL
40	1		*FRONT DASHBOARD FASCIA	Not Damaged	1,098.50 FL	*- FL
41	1		*FRONT DASHBOARD GLOVE BOX	Not Damaged	180.00 FL	*- FL
42	1		*FRONT DASHBOARD REINFORCEMENT	Not Damaged	500.00 FL	*- FL
43	1		*A/C BLOWER ASSY	Broken	1,284.00 FL	*1,098.70 FL
44	1		*A/C COOLING COIL ASSY	Broken	2,940.00 FL	*1,200.00 FL
45	1		*HEATER UNIT	No such part	1,013.00 FL	*- FL
46	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
47	1		*BONNET SEALANT	Necessary	100.00 FS	*40.00 FS
48	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
49	1		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
50	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
51	1		*FRONT SUPPORT PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
52	1		*FRONT SUPPORT PANEL TOP COVER CLIPS	No such part	50.00 FS	*- FS
53	1		*FRONT WHEEL HOUSE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
54	1		*FRONT WHEEL HOUSE PANEL INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
55	2		*FRONT DOOR SEALANT	Not Necessary	200.00 FS	*- FS
56	2		*HEADLAMP CLIPS	Necessary	100.00 FS	*60.00 FS
57	1		*COOLANT	Necessary	80.00 FS	*40.00 FS
58	1		*A/C FLUID	Necessary	80.00 FS	*40.00 FS
59	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
60	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	29,573.00	12,863.65
- List Item Discount on L Items 25.00/25.00% (\$)	7,080.75	3,130.91
Total Parts (\$)	22,492.25	9,732.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R BONNET COMPONENT	New	150.00	60.00
2	R&R RADIATOR	New	150.00	80.00
3	R&R A/C CONDENSER	New	150.00	80.00
4	R&R INTERCOOLER	New	150.00	70.00
5	R&R WIPER WASHER TANK	New	100.00	30.00
6	R&R RADIATOR SPARE TANK	New	100.00	30.00
7	WHEEL ALIGNMENT	New	180.00	0.00
8	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
9	R&R DASHBOARD FASCIA	New	450.00	250.00
10	R&R A/C BLOWER ASSY	New	150.00	80.00
11	R&R A/C COOLING COIL ASSY	New	150.00	80.00
12	CHECK WIRING	New	100.00	60.00
13	UPHOLSTERY	New	300.00	0.00
14	PANEL BEAT	New	2,000.00	1,400.00
15	RUST PROOFING	New	200.00	80.00
16	SPRAY PAINTING	New	2,000.00	1,400.00
Gross Labour Cost (\$\$)			6,630.00	3,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >